

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305418585
 REGN NO : SHD4181T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 07.11.2019
 DATE/TIME IN : 24.08.2020 11:00
 ACCIDENT DATE : 23.08.2020

NTUC-OP/P)
 LKK-Taufik

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	df
0002 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	cut
0003 04-01-0104-2532-G	REAR BUMPER SIDE BRKT RH	1	33.10	20.00	26.48	Xmm
0004 04-01-0104-0852-G	REAR BUMPER REFLECTOR RH	1	31.90	20.00	25.52	cut
0005 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	new
0006 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00	Xmm 771.64

SUB-TOTAL : 960.12

JOB NATURE

0000 PB	PANEL BEATING	350.00	320
0001 SP	SPRAYPAINT CHARGE	250.00	200
0002 L	R/I REVERSE SENSOR	120.00	30

SUB-TOTAL : 720.00

\$1321.64
 * 2 days

Taufik 97445749
 'WP' 24/8/2020 4pm
 02 days
 P/p Repairing after repair
 Taufik@Kuantan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: