

COMFORTDELGRO ENGINEERING PTE LTD

Date: 24.08.2020

REPAIR ESTIMATE

Time: 14:50:26

Page: 1

China Taiping CP
LTC - Tanfich

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305418586

REGN NO : SHB4723R

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : IONIQ(G2)

DATE OF REGN : 26.06.2019

DATE/TIME IN : 24.08.2020 11:10

ACCIDENT DATE : 23.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0592-G	FRT DOOR RH	1	1,797.20	20.00	1,437.76	H ✓
0002 04-01-0104-2468-G	FRT DOOR PROTECTOR RH	1	116.20	20.00	92.96	cut -
0003 04-01-0104-0595-G	REAR DOOR RH	1	1,789.90	20.00	1,431.92	RY
0004 04-01-0104-0810-G	ROCKER PANEL GARNISH RH	1	290.00	20.00	232.00	RY
0005 28-01-0103-0007-A	Frt Door ComfortDelGro RH	1	75.00	2.00	75.00	nei ✓
0006 28-01-9999-2024-A	Rear Door APPS Sticker RH	1	80.00	0.20	80.00	m ✓

SUB-TOTAL : 3,349.64

JOB NATURE

0000 PB	PANEL BEATING	350.00	320
0001 SP	SPRAYPAINT CHARGE	750.00	600
0002 20-00	TUFF COAT ON AFFECTED PARTS.	60.00	30
0003 L	TRANSFER OF DOORS	240.00	60

SUB-TOTAL : 1,400.00

Tanfich 974157491
 'WP' 24/8/2005
 p/p Resurvey before paint
 2 days
 Tanfich C. Chuan

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 24.08.2020

REPAIR ESTIMATE

China Taiping CP/P

Time: 14:50:26

Page: 2

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

Lee - Taufik

JOB NO : 305418586
REGN NO : SHB4723R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 26.06.2019
DATE/TIME IN : 24.08.2020 11:1
ACCIDENT DATE : 23.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Lmf

TOTAL : 4,749.64

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 8280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

343 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Upper Road Singapore 210449

24 Seroko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 24.08.2020 14:20

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO.: 305418586

OWNER

IS CITYCAB PTE LTD
OWNER NO. 7010070
LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188

(R) (O)
(P)

JUNT CARD NO.

REGN NO.

SHB4723R

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 24.08.2020 11:10

YR OF MANU.

26.06.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164515


COMPLETION DATE/TIME:

Accident Date: 23.08.2020

NATURE: 3P 23.08.2020

JOB DESCRIPTION

3/NO LABOR CODE DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Slip

Exit Pass

Vehicle No.: SHB4723R

LIMITS

Vehicle No.:

SHB4723R

Service Advisor

Signature/Date

Name of Service Advisor

Date