

ASS. REC. BY:

REF:

LPC 20009027/Kg

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV

REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GX 89214

Yr Regn:

07 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Cobster

c.c

2953

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

158254

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD A / Rim or

Tire Size:

ONYX

195R15X8

Green Max

165R15X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

9/8/20

Rear

R/Bal.

6

mm

L/Bal.

6

mm

D.O.I.

27/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

191 N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/12

15,800 confirmed checked 14,307.45, 48%

Date/Time, File Pass to?

☐

Prel. Report

1) 29/12 11:30

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

14

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

DD

Lump Sum / I.B.I. (\$

...CLAIM SUBFOLDER...(Pending for Approval)

LN

OD Longpac

CLAIM SUBFOLDER TRACKING

Case	Notified	Estimates	Est. Submitted	Adj. Assigned	Ins. Auth. No.	Status
Main	26 Aug 2020 11:51		26 Aug 2020 13:57 S\$30,107.45			Pending for Approval

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	DONG CONSTRUCTION & ENGINEERING PTE LTD, Co. Reg. No.: 201216270E				
Vehicle Reg. No.:	GX892H		Date of Loss:	09/08/2020 04:00 - :59 [48 Months and 12 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD		Policy/Cover Note No.:	Z/20/VC00/107557 (Comprehensive)	
			Excess:		
Repairer:	K Kim Hin Auto Pte Ltd (HQ) PROFILE 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018				
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388				
Driver/Custodian:	TAN SIM HUA (47 / Male) , NRIC: S7311506Z, Tel: +6597168733 Email: NOEMAIL				

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/20/VC00/107557	Date of Loss:	09/08/2020
Vehicle Reg. No.:	GX892H	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	DONG CONSTRUCTION & ENGINEERING PTE LTD		
Driver:	TAN SIM HUA		

Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Vehicle Reg. Date:	28/07/2016
Vehicle Colour:	WHITE		
Engine No:	ZD30013934N	Chassis No:	ZD30013934N
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) ~~18~~ 14 days



*Not Authorised
L1 Imp &
Repair After Repair
Ex B1200*

Description of Accident/Loss PLEASE REFER TO SKETCH PLAN

Remarks: VEHICLE IS IN THE WORKSHOP. PLS ARRANGE FOR SURVEY. THANK YOU -
SANDRA

Present Location: K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	23,827.45
Miscellaneous Items	0.00
Labour	6,280.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	30,107.45
+ GST 7.00% (S\$)	2,107.52
Nett Amount (S\$)	32,214.97

This claim is handled by: SANDRA KHONG YEE TENG

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Aug 2020)

Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GX892H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER C/W REINFORCEMENT	B ₁ 0.00	0.00	*520.00 F	✓
2	2		*FRONT BUMPER BRACKET LH/RH	B ₁ 0.00	0.00	*120.00 F	✓
3	1		*FRONT GRILLE	M ₁ 0.00	0.00	*255.00 F	✓
4	1		*FRONT GRILLE LOGO	M ₁ 0.00	0.00	*40.00 F	✓
5	1		*FRONT GRILLE INNER BRACKET	B ₁ 0.00	0.00	*60.00 F	✓
6	10		*FRONT GRILLE CLIPS	M ₁ 0.00	0.00	*30.00 F	✓
7	1		*FRONT GRILLE INNER CROSS MEMBER	R 0.00	0.00	*245.00 F	✓
8	1		*N/S HEADLAMP ASSY	CM 0.00	0.00	*250.00 F	✓
9	1		*N/S HEADLAMP LOWER APRON GARNISH	D ₁ 0.00	0.00	*65.00 F	✓
10	1		*FRONT PANEL	B ₁ 0.00	0.00	*640.00 F	✓
11	1		*FRONT PANEL CABSTAR EMBLEM	M 0.00	0.00	*35.00 F	✓
12	1		*FRONT WIPER PANEL	B ₁ 0.00	0.00	*340.00 F	✓
13	1		*FRONT WIPER PANEL LOWER MOULDING	Sm 0.00	0.00	*35.00 F	✓
14	1		*N/S FRONT CORNER PANEL	B ₁ 0.00	0.00	*200.00 F	✓
15	1		*N/S FRONT CORNER PANEL BRACKET	B ₁ 0.00	0.00	*125.00 F	✓
16	1		*N/S WINGMIRROR STAY	B ₁ 0.00	0.00	*145.00 F	✓
17	1		*N/S WINGMIRROR OUTER GARNISH	M ₁ 0.00	0.00	*95.00 F	✓
18	1		*N/S WINGMIRROR STAY CAP COVER	CM 0.00	0.00	*24.00 F	✓
19	1		*N/S WINGMIRROR STAY INNER COVER	M ₁ 0.00	0.00	*24.00 F	✓
20	1		*FRONT WINDSCREEN GLASS	CM 0.00	0.00	*680.00 F	✓
21	1		*FRONT WINDSCREEN GLASS LOWER MOULDING	M 0.00	0.00	*35.00 F	✓
22	2		*FRONT WINDSCREEN GLASS SIDE MOULDING LH/RH	M 0.00	0.00	*130.00 F	✓
23	2		*FRONT WIPER ARM LH/RH	N/S B ₁ 0.00	0.00	*190.00 F	4
24	2		*FRONT WIPER BLADE LH/RH	N/S C ₁ 0.00	0.00	*70.00 F	4
25	1		*FRONT WIPER LINKAGE	Sm 0.00	0.00	*95.00 F	✓
26	1		*FRONT WIPER MOTOR	Sm 0.00	0.00	*350.00 F	✓
27	1		*N/S DOOR A PILLAR - OUTER	B ₁ 0.00	0.00	*940.00 F	✓
28	1		*N/S DOOR INNER STEP PANEL	D ₁ 0.00	0.00	*165.00 F	2
29	1		*N/S DOOR INNER UPPER PILLAR	B ₁ 0.00	0.00	*285.00 F	2
30	1		*N/S FRONT DOOR	B ₁ 0.00	0.00	*680.00 F	✓
31	1		*N/S FRONT DOOR SIGNAL LAMP	M ₁ 0.00	0.00	*35.00 F	✓
32	2		*N/S FRONT DOOR HINGES (TOP/LOWER)	B ₁ 0.00	0.00	*100.00 F	✓
33	1		*N/S FRONT DOOR CHECKER	D ₁ 0.00	0.00	*45.00 F	✓
34	1		*N/S FRONT DOOR STEP GARNISH	CM 0.00	0.00	*120.00 F	✓
35	1		*N/S FRONT DOOR STEP GARNISH BRACKET	R 0.00	0.00	*135.00 F	✓
36	1		*N/S FRONT DOOR LOCK	T ₁ 0.00	0.00	*130.00 F	✓
37	1		*N/S FRONT DOOR LOCK CATCH	R 0.00	0.00	*30.00 F	✓
38	1		*N/S FRONT DOOR WEATHERSTRIP	D ₁ /C ₁ 0.00	0.00	*100.00 F	✓
39	1		*N/S FRONT DOOR FRAME WEATHERSTRIP	Sm 0.00	0.00	*95.00 F	✓
40	1		*N/S FRONT DOOR OUTER MOULDING	B ₁ 0.00	0.00	*90.00 F	✓
41	1		*N/S FRONT DOOR INNER MOULDING	Sm 0.00	0.00	*55.00 F	✓
42	1		*N/S FRONT DOOR REGULATOR	B ₁ 0.00	0.00	*95.00 F	✓
43	1		*N/S FRONT DOOR REGULATOR MOTOR	T ₁ 0.00	0.00	*340.00 F	✓
44	1		*N/S FRONT DOOR LOWER SEAL	D ₁ 0.00	0.00	*30.00 F	✓
45	1		*N/S FRONT DOOR INNER TRIMBOARD	B ₁ 0.00	0.00	*420.00 F	✓
46	1		*N/S FRONT DOOR INNER ARCH PANEL GARNISH	Sm 0.00	0.00	*80.00 F	✓
47	1		*DASHBOARD TOP - LH	D ₁ 0.00	0.00	*300.00 F	✓
48	1		*DASHBOARD TOP - CENTRE	D ₁ 0.00	0.00	*300.00 F	2

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
49	1		*DASHBOARD TOP - RH	Nel	0.00	0.00	*300.00 F	✓
50	1		*DASHBOARD TOP TOP INNER	Sm	0.00	0.00	*350.00 F	✓
51	1		*N/S DASHBOARD TOP SIDE COVER	Sm	0.00	0.00	*60.00 F	✓
52	1		*N/S DASHBOARD LOWER COVER	Sm	0.00	0.00	*120.00 F	✓
53	1		*N/S DASHBOARD LOWER LID GLOVE BOX	Sm	0.00	0.00	*145.00 F	✓
54	1		*N/S DASHBOARD CUP HOLDER FINISHER	Sm	0.00	0.00	*70.00 F	✓
55	1		*DASHBOARD CENTRE LOWER GARNISH	Sm	0.00	0.00	*220.00 F	✓
56	1		*DASHBOARD CENTRE LOWER GLOVE BOX	Nel	0.00	0.00	*150.00 F	✓
57	1		*DASHBOARD REINFORCEMENT	Bj	0.00	0.00	*480.00 F	✓
58	2		*FRONT CABIN MOUNTING BUSH	DTI	0.00	0.00	*110.00 F	✓
59	2		*REAR CABIN MOUNTING	DTI	0.00	0.00	*100.00 F	✓
60	1		*FRONT CABIN TILT SHAFT	Bj	0.00	0.00	*450.00 F	✓
61	1		*FRONT CABIN TILT INNER SHAFT	Bj	0.00	0.00	*295.00 F	✓
62	1		*FRONT CABIN TILT STAY	DTI	0.00	0.00	*120.00 F	✓
63	1		*CABIN TILT OUTER PULL LEVER	Sm	0.00	0.00	*145.00 F	✓
64	1		*CABIN TILT OUTER PULL LEVER LINKAGE	Sm	0.00	0.00	*90.00 F	✓
65	2		*FRONT CABIN MOUNTING BRACKET LH/RH	DTI	0.00	0.00	*390.00 F	✓
66	1		*AIR CON CONDENSER	Pur	0.00	0.00	*550.00 F	✓
67	1		*AIR CON FAN ASSY	CMA	0.00	0.00	*380.00 F	✓
68	1		*AIR CON LIQUID PIPE	Nel	0.00	0.00	*210.00 F	✓
69	1		*AIR CON DISCHARGE PIPE	Bj	0.00	0.00	*230.00 F	✓
70	1		*AIR CON DRYER RECEIVER	Bj	0.00	0.00	*135.00 F	✓
71	1		*AIR CON SUCTION PIPE	Bj	0.00	0.00	*125.00 F	✓
72	1		*AIR CON BLOWER	Sm	0.00	0.00	*480.00 F	✓
73	1		*AIR CON COOLING COIL	Sm	0.00	0.00	*1,150.00 F	✓
74	1		*AIR CON COOLING COIL INLET HOSE	Sm	0.00	0.00	*70.00 F	✓
75	1		*AIR CON COOLING COIL OUTLET HOSE	Sm	0.00	0.00	*70.00 F	✓
76	1		*AIR CON HEATER UNIT	Sm	0.00	0.00	*820.00 F	✓
77	1		*TURBO COOLER	Pur	0.00	0.00	*1,450.00 F	✓
78	1		*RADIATOR ASSY	Pur	0.00	0.00	*580.00 F	✓
79	1		*RADIATOR FAN BLADE	DTI	0.00	0.00	*125.00 F	✓
80	1		*RADIATOR FAN CLUTCH	Sm	0.00	0.00	*310.00 F	✓
81	1		*RADIATOR FAN COWLING - TOP	CMA	0.00	0.00	*55.00 F	✓
82	1		*RADIATOR FAN COWLING - LOWER	CMA	0.00	0.00	*55.00 F	✓
83	2		*RADIATOR MOUNTING	CMA	0.00	0.00	*170.00 F	✓
84	2		*GEARBOX MOUNTING	CMA	0.00	0.00	*180.00 F	✓
85	1		*REAR VIEW MIRROR	miy	0.00	0.00	*195.00 F	✓
86	1		*FRONT NUMBER PLATE	Sm	0	0.00	*30.00 FS	✓
87	1		*FRONT PANEL HEAT INSULATION	Sm	0	0.00	*150.00 FS	✓
88	1		*FRONT WINDSCREEN GLASS SEALANT	40Sm	0	0.00	*60.00 FS	✓
89	1		*FRONT WINDSCREEN GLASS DAMPING SEAL	Sm	0	0.00	*20.00 FS	✓
90	1		*ERP BRACKET	Sm	0	0.00	*26.00 FS	✓
91	1		*N/S FRONT DOOR INNER SPEAKER	Sm	0	0.00	*120.00 FS	✓
92	1		*N/S FRONT DOOR ROC STICKER	Sm	0	0.00	*25.00 FS	✓
93	1		*RADIATOR COOLANT	Sm	0	0.00	*48.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	20,782.00
+ Margin on L,N Items 15.00% (\$\$)	3,045.45
Total Parts (\$\$)	23,827.45

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab. Type	Amount
<u>Labour Items</u>			<i>1600</i>
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	New	2,000.00
2	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	100.00 ✓
3	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUM AND RECHARGE GAS	New	100.00 ✓
4	TO REMOVE DOORS FITTINGS	New	<i>60</i> 80.00
5	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER	New	<i>1400</i> 1,600.00
6	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS	New	<i>250</i> 280.00
7	TO REMOVE FRONT BRAKE BOOSTER, BRAKE MASTER PUMP AND STEERING COLUMN	New	<i>60</i> 120.00
8	TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	<i>nn</i> 80.00 X
9	TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE REPAIRING WORKS	New	<i>80</i> 120.00
10	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	<i>1200</i> 1,800.00
Gross Labour Cost (\$\$)			6,280.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/08/2020 14:35
Date Of Accident	09/08/2020 04:30
Exact Location Of Accident	ALONG GEYLANG LORONG 22
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX892H
-----------------------------	--------

Insured/Policyholder

Name Of Registered Owner	DONG CONSTRUCTION & ENGINEERING PTE LTD
Co Reg No	2XXXXX270E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93809333

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 5M/T ABS 2DR 2WD EURO 5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/20/VC00/107557
Cover Note Number	

Driver

Name of Driver	TAN SIM HUA
NRIC No	SXXXX506Z
Date Of Birth	02/04/1973
Occupation	INDOOR
Date Of Driving Pass	22/05/1995
Driving Experience	25 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97168733
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 235 LORONG 8 TOA PAYOH #09-92
Postcode	310235
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB7916C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


24.8.2020 @ 11.40 AM



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, vehicle A was travelling along Geylang Lorong 30. Vehicle B stop at the traffic light junction, vehicle A can't stop in time and collided onto vehicle B. My vehicle could not start after the accident then it was towed to the police compound. I only manage to tow out my vehicle on 24/8/20. This is why I am making this 1st accident report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: