

ASS. REC. BY: PomeREF: CCY/AM 20009041es37222

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐To Inspect Vehicle No: FBQ 7803Rat Workshop m/s TEAMWORKof 53, ubi nr 1 #01-23Insured: AK

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 9K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBQ 7803R Yr Regn: 2019 / DBLType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: YAMAHA JUPITER 115 21 c.c. 114Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 1757 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH 34E1120K J233276Gen. Cond: Good ☒ / Fair ☐ / Poor ☐ / Burnt ☐Steering: Order / Jammed / Leaked / Burnt or _____Brake: Order / Jammed / Leaked / Burnt or _____Modi: Nil ☒ / S/Rim ☐ / STD A/Rim or _____Tyre Size: F: 70/90-17R: 80/90-17BS / DUN / EXNOVA / GY / FS / LIZA ☒ MICH ☐ OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 3 mm R/Bal. 3 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 24/08/2020 D.O.I. 27/08/2020Survey held at TEAMWORK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR 2 O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐
☐

: Prell. Report

: Final Report

1) _____

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.I. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐
☐
☐
☐

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Company

Owner ID: 722Z

Vehicle No.: FBQ7803R

Vehicle to be Exported: No

Intended Deregistration Date: 27 Aug 2020

Vehicle Make: YAMAHA

Vehicle Model: JUPITER 115 Z1

Primary Colour: Red

Manufacturing Year: 2019

Engine No.: E3R5E0245062

Chassis No.: MH3UE1120KJ233276

Maximum Power Output: -

Open Market Value: \$1,498.00

Original Registration Date: 13 Dec 2019

First Registration Date: 13 Dec 2019

Transfer Count: 1

Actual ARF Paid: \$225.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Dec 2029

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$3,921.00

COE Rebate Amount: \$3,642.00

Total Rebate Amount: \$3,642.00

The information contained herein is correct as at 27 Aug 2020

OK