

(C488) 186-CP1P) Jy
Date: 26.08.2020
Time: 16:17:32
Page: 1

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305418859
REGN NO : SHA5730T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 18.04.2019
DATE/TIME IN : 26.08.2020 13:35
ACCIDENT DATE : 26.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	repair
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	cm ✓
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	2 ne ✓
0004 04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50	20.00	161.20	2 ?
0005 04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00	?
0006 04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04	X
0007 04-01-0104-2288-G	BEAM-RR BUMPER	1	294.80	20.00	235.84	?
0008 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00	X
0009 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	0.20	135.70	sc ✓

SUB-TOTAL : 1,531.90

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE

~~400.00~~ 320
~~300.00~~ 200

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

ELGRO ENGINEERING
Date: 26/08/2020
Time: 11:15
Page: 2
COMFORTDELGRO
ARC Repair
COMFORT
383
SIN
6

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO
REGN NO
MILEAGE
MAKE
MODEL
DATE OF REGN
DATE/TIME IN
ACCIDENT DATE

30%
SHA:
000000
HYUNDAI
IONIQ
18.04.2018
26.08.2020
26.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 17-01 CHECK ALL LIGHTING
0003 L REMOVE/REFIX REVERSE SENSOR

50.00 ~~30~~
80.00 ~~50~~

SUB-TOTAL : 830.00

TOTAL : 2,361.90

MVA NAME & SIGNATURE
DATE :

RASHL - Hp 90010068
SURVEYOR NAME & SIGNATURE
DATE : 27/08/2020 @1430

AUTHORISED : YES / NO

3 days
P/P
Resurvey before repair

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Type: M/Car / M/Cycle / Bus / Van / Truck / Trailer of
LTP RES / OD RES / EVA / INV / MV

16.08.2020
16:17:32
COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579791

Mainline : 65 6383 6280 Fax/Hotline : 65 6280 9755

Workshops

54 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 209286

120 Ulu Pandan Singapore 119149

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728731

501 Yishun Industrial Park A Singapore 758732

Date/Time: 26.08.2020 16:00

Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305418859


COMER	REGN NO. SHA5730T	MILEAGE
AS COMFORT TRANSPORTATION PTE LTD	MAKE : HYUNDAI	FUEL
7010045		E.....1/2.....F
383 SIN MING DRIVE	MODEL IONIQ(G2)	DATE/TIME IN 26.08.2020 13:35
Singapore SINGAPORE 575717	YR OF MANU. 18.04.2019	TARGET DATE
65508755 (R) (P)	CHASSIS CODE KMHC851CVKU141702	COMPLETION DATE/TIME:
OUNT CARD NO.		

Accident Date: 26.08.2020

NATURE: 3P 26.08.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



Worked & Passed Out By:

Record)

Sh:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Condition) ledgement Slip

Exit Pass

he veh has

repair at th

arket Value:

dent Rport:

Seen: f Service Advisor

rs: turned to Service Reception upon collection

EV / REF

Vehicle: IN / OUT

Person Contacted:

Vehicle No.:

SHA5730T

Name of Service Advisor

Date

To be kept by Security Guard

The I/C / Chassis frame / Body Structure affected due to collision