ASS. REC. BY: A MEET: CS/CT1200	109062/Risf3 1 664B
	GNMENT
From: Date:	Veh No: SMG 73952 Yr Regn: 2018 / DEC Type: (I.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost:	Truck / Trailer or
OD I P WS / TP RES / OD RES / EVA / INV / MV	200
To Inspect Vehicle No: SMG 73957	1.12.4.11.11.12
at Workshop m/s Volkswarch	Golddi Dag
of 241, NExamer en	obusceound TO fire
Insured: CT1	Eng/No:
Policy No.	CINO: IMBBP TNE 250 362849
Claims No.	Gen. Cond: Good / Call / Poor / Burnt
Sum Insured: Excess:	Steering: Inorde / Jaimmed / Leaked / Burnt or
(Client's Record)	Brake: Norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205 55R16
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 76K	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. A mm R/Bal. A mm
	L/Bal. L mm U/Bal. G - mm
	D.O.A. 25/06/2020 D.O.I. 28/08/2020
	Survey held at Vousswern
Lum Sum: % · 3 Val.: Yes or No	(Mark 1917) (Mark 1919) (Mark 1919)
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	<u> </u>
hand lint - 43K	
,	
<u>*</u>	
Dale/Time, File Pass to? : Prell. Report	Days Of Repair:
. , rom Ropore	
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
Add I	page 1
2)	Transition of the state of the
	: Interview (\$) Photos
Reput Formal:	: Tech. Invs (\$) others
Lump Sun / f.B.f: (%)	:Weellend (\$)
•	TOTAL

# ŠKODA Centre Singapore

26 Leng Kee Rd Singapore 159104 Biz. Reg. No.: 199101494Z GST No.: M200985052







# Quotation

Non binding - Preview

Company CHINA TAIPING INSURANCE (S) PL 3 ANSON ROAD #18-00 SPRINGLEAF TOWER Singapore 079909

Customer Details: Mr BENJAMIN TINDALL 79E TOA PAYOH CENTRAL #02-61 Singapore 315079

1/2 Page Document no. Document date 26-08-2020 Customer no. 5211001170 Customer GST-ID 200208384E Dealer 30001 2020020296/1 Job order number 26-08-2020 CHARMAINE KONG Job order date Service Advisor

Mileage First registration License plate Model code Octavia Ambition 1.0 I TSI 85kW DSG 11,441 TMBBP7NE2J0362849 28-12-2018 SMG7395Z 5E33BD

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Wheel Alignment	1	pcs.	360.00	#1	360.00	
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	4	pcs.	280.00	#1	280.00	299.60
	R&R RIM & BALANCE	1	pcs.	50.00	#1	50.00	53.50
	R&R REAR AXLE BEAM	3	pcs.	840.00	#1	2,520.00	2,696.40
	R&R CTR CONSOLE TO R&R ?	1	pcs.	840.00	#1	840.00	898.80
	HANDBRAKE CABLE		pus.	040.00			
5E5833051B	Door 711	1	pcs.	3,040.00	#1	3,040.00	3,252.80
	(LHR Door) 751	121				00.40	400.00
5E5839697C	Door Seal, DOOR SEAL LOWER LH	1	pcs.	99.40	#1	99.40	106.36
	DOOR SEAL LOWER LH				0.000		75.44
5E0839717B 5AP	Door Seal 7 % /	1	pcs.	70.20	#1	70.20	75.11
	LHR DOOR SEAL (SIDE))			Trans.	200	002022	
5J0867276	DOOR SEAL LOWER LH Door Seal LHR DOOR SEAL (SIDE)	6	pcs.	1.70	#1	10.20	10.91
	DOOR BOARD CLIP )			022202	2200		
323863950	Sound Absorber 3 ALL DOOR INSULATOR Primed Primed	1	pcs.	67.14	#1	67.14	71.84
5G0837205N GRU	Door Handle Outer Primed Paper	1	pcs.	172.96	#1	172.96	185.07
5E5807421G	Cover For 7.	1	pcs.	1,240.00	#1	1,240.00	1,326.80
5E5807393B	Guida Piac	1	pcs.	43.40	#1	43.40	46.44
0200070000	BUMPER SIDE BRACKET LH						
5E0810969C	Wheelhouse 7.7	1	pcs.	107.00	#1	107.00	114.49
0200.0000	LHR FENDER LINER 7 .		NAME OF THE PARTY				
5E5809601D	Sectional 11	1	pcs.	1,130.00	#1	1,130.00	1,209.10
	(LHR FENDER) 7 but		8				
D 180003M2	2k-Body Adhesive	1	pcs.	406.76	#1	406.76	435.23
D 506KD1A4	2k-Füllschaum	1	pcs.	144.94	#1	144.94	155.09
D 007500A2	Zinc Spray A	1	pcs.	62.88	#1	62.88	67.28
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	61.67	#1	61.67	65.99
5E0807905A	Protective 1	1	pcs.	50.30	#1	50.30	53.82
	LHR FENDER FILM 7		M15/5/5				1000104000
311601361	Rubber Valve AL	1	pcs.	3.29	#1	3.29	3.52
5E0601025BJ8Z8	Alloywheel Set 2	1	pcs.	1,105.00	#1	1,105.00	1,182.35
5Q0501049BL	Rear Axle Beam 7	1	pcs.	2,507.42	#1	2,507.42	2,682.94
5Q0501117D	Stub Axle ?	1	pcs.	275.33	#1	275.33	294.60
8V0598611A	Wheel Bearing With Mounti .	1	pcs.	575.29	#1	575.29	615.56 5,392.80
	LABOUR	185	pcs.	840.00	#1 724	5.040 00	4,280.00
	Spray Painting	5	pcs.	800.00		20 84000	898.80
	R&R REAR LUGGAGE TRIM	1	pcs.	840.00	#1 <b>(</b>	20 840.00	898.80
	R&R REAR SEAT	1	pcs.	840 00	#1 <b>Y</b>	840.00	
	REAR WATER LEAK TEST	1	pcs.	840.00	#1 <b>Y</b> :	840.00	898.80
	TRANSFER DOOR MECHANISM	1	pcs.	840.00	w. T.	70.00	000.00

# ŠKODA Centre Singapore

26 Leng Kee Rd Singapore 159104

Biz. Reg. No.: 199101494Z GST No.: M200985052





2/2



## Quotation

Non binding - Preview

Company CHINA TAIPING INSURANCE (S) PL

3 ANSON ROAD #18-00 SPRINGLEAF TOWER

Singapore 079909

Customer Details:

Mr

BENJAMIN TINDALL

79E TOA PAYOH CENTRAL

#02-61

Singapore 315079

Page

Document no.

Document date Customer no.

Customer GST-ID

Dealer

Job order number

Job order date Service Advisor 26-08-2020 5211001170

200208384E

30001

2020020296/1

26-08-2020 CHARMAINE KONG

License plate SMG7395Z

Model code 5E33BD

First registration 28-12-2018

TMBBP7NE2J0362849

Model

Octavia Ambition 1.0 I TSI 85kW DSG

Mileage

11,441

Tax Code #1

Labour 4,530.00

Material

23,573.18

GST %

7%

1,967.22

GST

Total amount excl. GST

28,103.18

Total amount incl. GST

30,070.40

Customer

Service Advisor

-VISIT OUR WEBSITE: aftersales.ww.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasme
Hp 900 100 68

9 days
28/08/2020
@ 1130
Rasy Sahn punt

/GS20073083 / Volkswagen Centre Singapore - HQ ÁTRY DATE & TIME: 26/08/2020 10:27 AUBMITTED BY: Charmaine Kong Mei Kwan

#### SINGAPORE ACCIDENT STATEMENT

MINA UNIBING

# 20296

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

## ACCIDENT STATEMENT

 Date Of Report
 26/08/2020 10:27

 Date Of Accident
 25/08/2020 10:20

 Exact Location Of Accident
 NEWTON CIRCUS

 Country/State of Loss
 SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMG7395Z

Insured/Policyholder

Name Of Registered Owner BENJAMIN TINDALL

NRIC No SXXXX664B

Email Address BENTINDALL@GMAIL.COM

Mobile Phone No (LOCAL) +65-88303201
Alternative Phone No OTHERS-88303201

Vehicle Particulars

Manufacturer SKODA

Model OCTAVIA AMBITION 1.0 L TSI 85KW DSG

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number MT/00746728

Cover Note Number

Driver

Name of Driver BENJAMIN TINDALL

 NRIC No
 SXXXX664B

 Date Of Birth
 20/03/1984

 Occupation
 INDOOR

 Date Of Driving Pass
 19/02/2019

Driving Experience 1 YEAR AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-88303201

Fax Number

Contact Number OTHERS-88303201

EMail Address BENTINDALL@GMAIL.COM

Address

postcode

79E TOA PAYOH CENTRAL #02-61 315079

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

**OWNER** 

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: ANG MINGLI ARABELLA BOGENE UY

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station Police Station Name

Police Station Address

ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING, POSTCODE: 319194, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2519999 - FAX NO: 63548749

TOA PAYOH NEIGHBOURHOOD POLICE CENTRE

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Refer to sketch plan. Insured has driver license in UK- UK license attached.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 111

Vehicle Registration Number

**GBJ5210B** 

Vehicle Make/Model/Colour **Details Of Properties** 

VAN

Vehicle Category

**GOODS VEHICLE** 

Name of Driver

NRIC/Passport Number

Contact Number

Address

Page 2 of 16

## Sketch Plan Pg. 1

#### **SKETCH PLAN**

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose(s) and the police in the purpose of the pu
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders

Bolfcyholder's Signature

Date & Time:

26/8/20

Driver's Signature

(If driver is not the policyholder)

Date & Time


Reporting Centre Personnel's Signature

Name

NRIC/FIN No.:

DSOS DUA 8 S

SKETCH PLAN



## **DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Refer	to	Police	report	# T/20200825/2060
			U	1
				8
DECLAR				

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

26/1/20

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

# Sketch Plan #3 Pg. 1





Police Station Of Origin: Toa Payoh N.P.C

93 To a Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 Tel No: 1800-2519999

# REPORT OF A TRAFFIC ACCIDENT

T/20200825/2060	
-----------------	--

1 of 3 Report No. T/20200825/2060

Date/Time 25/08/202	e Report M 20 13:41	ade:	Vide Report No.:	Station Diary No.: 73
informan	t's Particu	lars a manufacture	The contract of the contract o	
	Informant: IN TINDAL	L	Address: APT BLK 79E TOA PAYOH ( 315079	CENTRAL #02-61 SINGAPORE
ID Type / NRIC NC	ID No.: 0 / S848266	64B	Contact No.: Home/Office:	Mobile: 88303201
Nationali BRITISH			Email:	
Sex: Male	Age:	Date of Birth: 20/03/1984	Type of Informant: Driver	
Race: Caucasi	an		Language: English	Institution / School Name:
Occupat SOLTW	tion: ARE ENGI	NEER	Driving Licence Information: Class: 3	Date of Expiry:
- A.				

Typ of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 25/08/2020 10:20	Type of Location Roundabout
Location: NEWTON CI	RCUS			
Weather:		Road Surface:	·	Road Speed Limit:
Clear		Dry		50 Km/h
				L

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBJ5210B	Van					0
SMG7395Z	Car	SKODA	OCTAVIA 1.0 TSI AMBITION (A)	Blue	Seriously Damaged	1

		And the second second second
Insurance No	Effective	Expiry Date
	Insurance No	Insurance No Effective





2 of :

Report No. T/20200825/206

Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 CONTINUATION OF REPORT

Tel No: 1800-2519999

etails of Vo	hicle Insurance	Insurance No	Effective	Expiry Date
/ehicle No.	Insurance Company		28/12/2019	27/12/2020
SMG7395Z	TOTAL PROPERTY OF THE PROPERTY	MT/00746728	20/12/2010	

tails of Person	IUADIAER		Section 1 Section 2	0.000000	
y Pedestrian In	rolved: No	I lice of	Pedestrian	Crossi	ng: NA
o of Pedestrians	Injured: NIL	USE OF	e constitue de la constitue de	name a des	the contract the contract of
iver			ID No.	T	S8482664B
ame	BENJAMIN TINDALL				
elated Vehicle	SMG7395Z (Car)	Contact No.  Class of Driving Licence & Expiry Date		88303201 Class: 3 Date of Expiry: NIL	
ospital/Clinic					
_	ļ	Date	Discharge	NIL	
Date Treatment	NIL stad Medical Leave NIL		ee of Injury	NIL	
No. of Days gra	nted Medical Leave NIL	and the same of	entra eta en la como de la como d El como de la como de		ental of the second
Passenger	ANG MINGLI ARABELLA	BOGENE UY	ID No		S8131807G
Name	ANG MINGLI ARABLEE	5002			
	SMG7395Z (Car)		Conta	ct No.	97259996
Related Vehicle	SIVIG73932 (Gai)				
Hospitai. Clinic	pitai/Clinic NIL			of g ce & y Date	Class: NIL Date of Expiry: NiL
		Date	e Discharge	NIL	
Date Treatme	nt   NIL ranted Medical Leave   NI		ree of Injury		· /¥

Erief Details. 7 the 26/08/2020 at about 1022hrs, I was driving my car bearing the registration plate number ₹ MG7395Z along the roundabout at Newton Circus when a van bearing the registration plate GBJ5210B tried to make a right turn from the left lane. The van collided on to the side of my car causing a big dent and large scratches on the left side of my car. I stopped my car and waited for him to stop as well, however the driver continued to make the right turn and left the scene.

was in the car with my wife namely Ang Mingli Arabella Bogene Uy. I have the recording of the accident an lodging this report for police assistance.





Policia Station Of Origin:

Toa Payoh N.P.C

93 Tpa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 CONTINUATION OF REPORT

Tel No: 1800-2519999

3 of 3

Report No. T/20200825/2060

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 3 NUR FITHRI BINTE MOHAMMED RIZAL	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/08/2020 13:41
Officer In Charge Of Case:	Classification Of Case:
SI CALESWARI PALANI Co tact No.: 65476902 SINGAPORE POLICE FORCE	SN 168
Authentication Stamp NP168 SIGNATURE	

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Owner ID:	Singapore NRIC 664B
DESCRIPTION OF THE SECTION OF THE SE	
Vehicle No.:	5MG7395Z
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Aug 2020
Vehicle Make:	SKODA
Vehicle Model:	OCTAVIA 1.0 TSI AMBITION (A)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CHZA58663
Chassis No.:	TMBBP7NE2J0362849
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$17,878.00
Original Registration Date:	28 Dec 2018
First Registration Date:	28 Dec 2018
Transfer Count:	o .
Actual ARF Paid:	\$17.878.00
	unda kulunga dalah kalan kulungan da kalan k
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2028
PARF Rebate Amount:	\$13,408.00
िर्मार्गार्गार्गा (स.क.) आहरति एक (राजकार हिंद्या क्षात्र का	usen en antenia eta eta alai den herraken era kiri era en eraken eraken eta eta eraken eraken eraken eraken er Eraken eraken
COE Category:	27 Dec 2028
COE Period(Years):	A - Car up to 1600cc & 97kW (130bhp)
QP Paid:	10
COE Rebate Amount:	\$23,568,00
Total Rebate Amount:	\$19,627.00

οк

