

ASS. REC. BY:

REF: EQ/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s 1 Two Leg Spray

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 05/26 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGG 8984 Yr Regn: 05, 06Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis c.c. 1598Colour: M. Gold A/C: Insured / Std / NI / NASp. Reading: 93193 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR0538 EC 10 F 117528Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD / Rim orTyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 26/8/20

Survey held at

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 27/8/2020

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Old Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

F - P - S

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL