

HWA SENG SPRAY PAINTING PTE LTD
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO : 202017045G)
 TEL : 64533100
 FAX : 62669932

Date of Accident: 26/08/2020
 Your Insured
 Vehicle No.: GBG 788A

Not Authorised
61 Day @ 3350.00
Returning After Paint
6 days

ESTIMATE REPAIR COSTS TO TOYOTA ALTIS REG. NO. : SGG 8984 M

1pc	O/S/F Door Run Channel	
1pc	O/S/F Door Glass	
1pc	O/S/R Door	
1pc	O/S/R Door Protector	
1pc	O/S/R Door Glass	
1pc	O/S/R Door Lock	
1pc	O/S/R Door Rubber	
2pcs	O/S/R Door Hinges	(\$76.50/pc)
1pc	O/S/R Door Protector Chrome	
1pc	O/S/R Door Sticker	
1pc	O/S/R Door Striker	
1pc	O/S/R Door Handle	
1pc	O/S/R Panel (FENDER)	
1pc	O/S/R Door P/W Motor	509.10
1pc	O/S/R Door P/W Regulator	
1pc	O/S/R Door Outer Moulding	
1pc	Rear Bumper	
1pc	Centre Pillar	

	<i>Shatter</i>	<i>in</i>	S\$	
			109.60	X
			434.20	✓
		<i>By</i>	881.90	X
		<i>new</i>	104.30	✓
		<i>in</i>	301.60	X
		<i>n</i>	220.80	X
		<i>in</i>	128.50	X
		<i>n</i>	153.00	X
		<i>By</i>	26.80	✓
		<i>new</i>	68.20	✓
		<i>new</i>	68.20	✓
		<i>new</i>	69.40	✓
		<i>By</i>	828.90	✓
		<i>By</i>	769.10	✓
		<i>in</i>	132.40	✓
		<i>By</i>	118.40	✓
		<i>in</i>	384.90	X
		<i>n</i>	346.30	X

5140.50
 Less : 25% 1285.13

3855.37

LABOUR & MISC CHARGES

Panel Knocking
 Spray Painting
 Wire Checking
 Inner Seal
 Computerised Wheel Alignment
 Sealant & Clip
 Labour to remove & install rear windscreen
 Labour to Transfer Door Time & Attach Panel

	1200.00	<i>800</i>
	1200.00	<i>750</i>
	50.00	<i>20</i>
<i>new</i>	60.00	<i>30</i>
<i>new</i>	120.00	<i>X</i>
<i>new</i>	80.00	<i>60</i>
	180.00	<i>120</i>
	100.00	<i>60</i>

TOTAL 6845.37

HWA SENG SPRAY PAINTING PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: