	SSIGNMENT
<u>Au</u>	
From: Date:	Veh No: SGS1238S Yr Regn: 31/01/2018
Estimated Cost:	Type: M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: BM W 5201 LED c.c 1998
at Workshop m/s	Colour Grey A/C: Insured / Std / NI / NA
of	Sp.Reading [982 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WBAJA12070BJ19136
Claims No.	Gen, Cond: Good (Fair) Poor / Burnt
Sum Insured: Excess:	Steering: Inorden/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /STRim / STD A/Rim or
	. Tyre Size: F: 245/45 \$\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\
(Policy Condition)	R: 245/45 R18
8	SX BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIRY SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs:days Res.: Yes or No	D.O.A. 27/08/2020 D.O.I. 31/08/2020
Lum Sum: % 3 Val.: Yes or No	Survey held at Eng Soon
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / C	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	Repair day - 3 day
MV:145,000	3-14
PV: 77,703	
NV:67,000	
A CONTRACTOR OF THE CONTRACTOR	
1	<u> </u>
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 3
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) 3/9/20-Typist Add I	Fee: : Site Insp (\$)s+Rs,si
	: Interview (\$) Photos
Report Format: DAR	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weel:end (\$)
	TOTAL

SINGAPORE ACCIDENT STATEMENT

- IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
 This Formula is a control of the control of the process. 2. This Form must be completed by the Policyholder and/or the Authorised Driver.

 3. Information. 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to 4. The issue repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting

 Any false reporting may be referred to the Police for investigation.
 This report will be gla Records Manager. 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

of the report being made available 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of the aforesaid.

	ACCIDENT STATEMENT
Date Of Report	28/08/2020 11:14
Date Of Accident	27/08/2020 10:20
Exact Location Of Accident	AT 21 TOH GUAN ROAD EAST (TOH GUAN CENTRE)
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SGS1238S
Insured/Policyholder	
Name Of Registered Owner	NEO MENG CHOO
NRIC No	SXXXX757H
Email Address	NEOMENGCHOO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97997669
Alternative Phone No	OFFICE-97997669
Vehicle Particulars	
Manufacturer	BMW
Model	520I LED NAV
Exact Purpose for which vehicle was being used time of accident	d at
Are you claiming under your own insurance police for repair to your vehicle?	cy NO
f No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPG20000789
Cover Note Number	
Driver	
Name of Driver	NEO MENG CHOO
NRIC No	SXXXX757H
Date Of Birth	20/01/1962
Occupation	INDOOR
Date Of Driving Pass	05/11/1979
Date Of Strains Driving Experience	40 YEARS AND 9 MONTHS
	FEMALE
Gender Mobile Number	(LOCAL) +65-97997669
Mobile Manua	
Fax Number Contact Number	OFFICE-97997669
Contact radies	NEOMENGCHOO@GMAIL.COM
EMail Address	Page 1

APT BLK 288C JURONG EAST STREET 21 #12-384

Address Postcode

603288

Was driver an employee of the Insured's Company NO

NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

OVVIVE

Vehicle

-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH CLAIMING WORKSHOP

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKL1534B

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

Contact Number

F.C. WOO

NRIC/Passport Number

98196058

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

MEI

SKETCH PLAN **DESCRIBE CIRCUMSTANCES OF THE ACCIDENT** Ococ 18 | F c : emiT & etcl trebicoA 1020 Accident Location: 21 Toh Guan Road East (Toh Guan Coults) I was driving straight along the mentioned location. buildenly I fest an impact on my RH parties. I noted that vehicle B had collided anto my vehicle when entering the Compark ☐ Reporting Only ☐ Own Damage ☐ Third Party ☐ Claim at other workshop (OD/IE) DECLARATION DECLARATION

**MORRANT NOTE:

In the local colors of the foregoing particulars are true in every respect. Reporting Centre Personnel's Signature Driver's Signature Policyholder's Ngriature (if driver is not the policyholder) Date & Time: Date & Time: NRIC/FIN No.:

GIANG SENSEMENTANDEN, VI.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	757H
Vehicle Details	
Vehicle No.:	SGS1238S
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Sep 2020
Vehicle Make:	B.M.W.
Vehicle Model:	520I LED NAV
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	18055126B48B20A
Chassis No.:	WBAJA12070BJ19136
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$47,763.00
Original Registration Date:	31 Jan 2018
First Registration Date:	31 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$58,869.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2028
PARF Rebate Amount:	\$44,151.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jan 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$47,390.00
COE Rebate Amount:	\$33,552.00
Total Rebate Amount:	\$77,703.00


The information contained herein is correct as at 02 Sep 2020

Consumer responsibled (Righted on (11)December (12)Idlaming (14)One columns J. (15)Odd Worlson Kight Portion NAC INC. Hem 1316 995 (27 Fri RII Door 991654 Fit RH Door Protector 1317 1318 991601 Fit RH Door Hinge 1319 991688 Fit RH Door Wing Mirror 1320 991883 For RH Door Garnish 1321 991639 Fri RH Door Glass Onter Moulding 1 (22 991588 Fri R1) Door Class futer Moulding 1323 991584 PYRH Door Glass 991595 Fre RH Door Glass Regulator 1324 991596 Frt RH Door Glass Regulator Motor 1325 991662 Frt RH Door Rubber 1326 1327 991636 Frt RH Door Outer Handle 991607 Frt RH Door Inner Handle 1329 991628 Frt RH Door Lock w/Key
1330 991624 Frt RH Door Lock 991562 Fit RH Door Central Lock 13.52 991675 Pit RH Door Switch 991617 Fri RH Door Inger Man Board 13.44 991568 Frt RH Door Checker 991575 Frt RH Door Felt 991688 Pri RH Door Wire Harness 1337 991683 Fit RH Door Window Gluss Pillar 1338 991640 Frt RH Door Outer Pillar 1339 991613 Frt RH Door Inner Pillar 1340 991646 Frt RH Door Pillar Inner Garnish 1341 990554 Centre Pillar RH 1342 990543 Centre Inner Pillar RH 1343 990518 Centre Pillar Upper Gamish RH 1344 990565 Centre Pillar Lower Garnish RH 1345 991670 Frt RH Door Step Ohrnish 1346 994058 Rocker Panel RH 994049 Rocker Panel Inner Panel RH 1348 994047 Rocker Panel Garnish RH 1 349 994055 Rocker Panel Outer Side Skirt RH 1:00% 991300 Frt Bumper 1906 991325 Frt Bumper Bracket 1007/ 991462 Fri Bumper Side Retainer 991433 Frt Bumper Reinforcement 10ff): 901468 Frt Bumper Sponge 원이네는 991427 Frt Bumper Protector 10 ld: 991301 Fit Bumper Moulding 10 5 991407 Frt Bumper Lower Spoiler 1030 991821 Fri RH Headlamp Assy 10報 995089 Fit RH Side Lamp 995071 Fri RH Fender 1:1:05 991744 Fri RH Fender Lamp 1107 991752 Fri RH Fender Protector 1108 RH Lower Moulding RH Lower Moulding Front 12H Wheel 171 BR

(y)	NAC INC Them
	11601
	1353 993228 Non RII Door Hinge
	Non Chi Door Greniel
-	1556 993229 Ip-
-	1 993289 Rear Divin
-	
7	
-	132/0 Kcar RH Door Owler Hand
	Take I INCH ICE Door luner Land
7	to a local cole
	1364 XXXXV Kcar R Door Impression David
1	The property of the second sec
-1	1366 993242 Para Distribution Channel
-	1367 993285 Rear RH Door Langle Garnish
-	1308 993288 Renr RH Door IVI CI
1	
	1371 993300 Per Ren Door Step Garnish
	1371 993309 Rear RH Door Switch 1994070 Roof Top Panel
	1300 Poor Real Door Switch 1904070 Roof Top Panel 1904098 Roof Top Moulding
	(IP)(IR) 994098 Roof Top Moulding (IR) 994085 Roof Top Air-bag
	994084 Roof Top Air L
	992976 Rear Burna B
	993045 D Sumper Side Retniner
li	993077 Rose D. Reinforcement
. 1	9930403 Rear Bumper Sponge
i	993026 Real Pumper Protector 993021 Paris Pumper Moulding
朝	1266 995 16/Res Pumper Lower Spailer
1	1268 995116 Rear RH Toillamp 1298 993456 Rear RH Funder
B	9934507 Rear RH Fender 990247 Sticker
1	990247 Sticker
-	
-	
-	
-	
-	
ļ	

Mo of Hener:

Assessor: Suppin



sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used brnw 520, brnw 520 Singapore, used brnw 520 Singapore, used brnw 520 Singapore or even buy used brnw 520 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2020 sgCarMart, Singapore. All rights reserved.