

Your Ref: SNM20D201330/C02/LEWLC

Date: 31st Aug 2020

Our Ref: CS1/CTI20009129/Etf3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJK 4920S
INSURED VEHICLE: PC 5675P
ACCIDENT DATE: 13/03/2020**

We thank you for your instruction on 28/08/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJK 4920S from M/s Aeon Auto Consultants LLP.
- b) Final Repair Bill of SJK 4920S from M/s V-Tech Auto Service.
- c) Singapore Accident Statement of Vehicles SJK 4920S and PC 5675P.
- d) Police Report of Vehicles SJK 4920S.
- e) Colour damaged vehicle photographs of SJK 4920S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJK 4920S
Make & Model	: Toyota Corolla Altis 1.6 Auto
Year of Registration	: 2008
Chassis Number	: MR053ZEE106119544
Engine Capacity	: 1598 cc

- 2. We recommend that the repairs of the entire damage require about 11 (Eleven) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.