

Surveys *Ross*

REF:

92268

LOG XPRY: 2023/m2


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SJH 24652**
 at Workshop m/s **AKA AUTO**
 of **25, KAKABUKIT RD, #02-36**
 Insured: **AKA**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SJH 54652** Yr Regn: **2008 / Auk**
 Type: ☒ M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **HONDA AIRWAVE / SMA** c.c. **1496**
 Colour: **GREEN** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **262323** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **9311300893**
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: **Inorder / Jammed / Leaked / Burnt** or
 Brake: **Inorder / Jammed / Leaked / Burnt** or
 Modi: **Nil / S/Rim / STD A/Rim** or
 Tyre Size: F: **175/60R15**
 R: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: **24K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **12** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 25/06/19	D.O.I. 27/06/19

Survey held at _____
 Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NO G3A
	Repair limit 9K
	Range of REPAIR COST - (6K - 8K)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: **12**

Resurvey No. of Trip: **1**

1)

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:
 Transportation:
 S + RS, SI
 Photos
 Others

Report Format : **DAR**

Lump Sum / I.B.I. (\$) _____)

TOTAL

180
11
191

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9226F
Vehicle Details	
Vehicle No.:	SJH5465Z
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	L15A5200927
Chassis No.:	GJ11300893
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,069.00
Original Registration Date:	13 Aug 2008
First Registration Date:	13 Aug 2008
Transfer Count:	0
Actual ARF Paid:	\$14,069.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$17,099.00
COE Rebate Amount:	\$14,102.00
Total Rebate Amount:	\$14,102.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Jun 2019

OK

24,000
14,102

9898