

ASS. REC. BY: Paul

REF:

CS/CTI 20009164/R11f3425E

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD 10813at Workshop m/s KAH MOTORof 235 ALKANDAA RDInsured: CTI

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 82K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMD 10813Yr Regn: 2018 / AUGType: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda HRV 1.5 LX CVTc.c 1496Colour: PURPLEA/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 029198T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: \_\_\_\_\_

C/No: JHMRU1830JX200113Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ SRim / ☐ STD A/Rim orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS: ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 28/08/2020D.O.L. 31/08/2020Survey held at KAH MOTORDes. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Finalised amount of \$ 16,349.53 / 8 days of repair is confirmed

(Red:9119.38;35%)

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: 8

1)

☐

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Rep. Form: \_\_\_\_\_

Lump Sum / L.B.A. (\$) \_\_\_\_\_

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : GOH GUO-HUA  
464 EAST COAST ROAD

SINGAPORE 429037

Registration No : SMD1081J

Chassis No : JHMRU1830JX200113

Model : HRV LX-SIN CVT YM 2018

Owner's Name : GOH GUO-HUA

Ins Policy No. :

Date of Accident : 28/8/2020

Document No. : SQT20002743

Page 1

Date : 29. Aug 2020

Customer No. : \*\*\*\*\*425E

Svc Advisor :

Engine No : L15B5670113

Date | Time : 29. Aug 2020 12:01:22 PM

Surveyor Name :

Survey Date :

Authorisation Date :

| Item     | Description                                        | Qty | Unit Price | Disc % | Amount  | 0% GST Amount | Amount incld GST |
|----------|----------------------------------------------------|-----|------------|--------|---------|---------------|------------------|
|          | TP DIRECT SETTLEMENT (J/NO: )                      |     |            |        |         |               |                  |
|          | OWNER:                                             |     |            |        |         |               |                  |
|          | OWNER INSURER:                                     |     |            |        |         |               |                  |
|          | ACC DATE:                                          |     |            |        |         |               |                  |
|          | SURVEYED BY:                                       |     |            |        |         |               |                  |
|          | DATE:                                              |     |            |        |         |               |                  |
|          | REF NO:                                            |     |            |        |         |               |                  |
|          | TP INSURER:                                        |     |            |        |         |               |                  |
|          | TP VEH:                                            |     |            |        |         |               |                  |
| BOSUN    | SUNDRIES                                           | 1   | 108.00     | 50     | 100.00  | 7.00          | 107.00           |
| BA02R    | REMOVE & RENEW REVERSE SENSORS-4 PCS (N)           | 1   | 180.00     | 150    | 180.00  | 12.60         | 192.60           |
| BOJSE    | BODY JOINT SEALANT REAR END PANEL                  | 1   | 100.00     |        | 100.00  | 7.00          | 107.00           |
| BOJSE    | BODY JOINT SEALANT REAR FLOOR PANEL                | 1   | 100.00     | X      | 100.00  | 7.00          | 107.00           |
| BOJSE    | BODY JOINT SEALANT TAILGATE                        | 1   | 100.00     |        | 100.00  | 7.00          | 107.00           |
| BML02I   | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER      | 1   | 180.00     | 150    | 180.00  | 12.60         | 192.60           |
| BMF00D   | RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)         | 1   | 650.00     | X      | 650.00  | 45.50         | 695.50           |
| BMI02D   | REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK      | 1   | 650.00     |        | 650.00  | 45.50         | 695.50           |
| BKTG02R  | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &  | 1   | 650.00     |        | 650.00  | 45.50         | 695.50           |
| BG02D    | REMOVE & INSTALL RR. WINDSCREEN.(N)                | 1   | 650.00     |        | 650.00  | 45.50         | 695.50           |
| BODAMKIT | WINDSCREEN DAM KIT.                                | 1   | 100.00     |        | 100.00  | 7.00          | 107.00           |
| BKRP02M  | CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN         | 1   | 8000.00    | 3250   | 8000.00 | 560.00        | 8560.00          |
| BP06R    | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1   | 3500.00    | 3120   | 3500.00 | 245.00        | 3745.00          |
| BKOT00R  | REMOVE & RENEW RR FLOOR INSULATOR.(N)              | 1   | 580.00     | X      | 580.00  | 40.60         | 620.60           |
| BC012R   | RESET VEHICLE SMART ENTRY SYSTEM                   | 1   | 650.00     | 580    | 650.00  | 45.50         | 695.50           |
| BC011R   | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA        | 1   | 650.00     | 580    | 650.00  | 45.50         | 695.50           |
| BMI03D   | REMOVE & INSTALL REAR COMPARTMENT LININGS          | 1   | 650.00     | 325    | 650.00  | 45.50         | 695.50           |

Printed on 29/8/2020 12:12:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

# HONDA

## KAH MOTOR CO. SDN. BHD.

(Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : GOH GUO-HUA  
464 EAST COAST ROAD

SINGAPORE 429037

Registration No : SMD1081J

Chassis No : JHMRU1830JX200113

Model : HRV LX-SIN CVT YM 2018

Owner's Name : GOH GUO-HUA

Ins Policy No. :

Date of Accident : 28/8/2020

Document No. : SQT20002743

Date : 29. Aug 2020

Customer No. : \*\*\*\*\*425E

Svc Advisor :

Engine No : L15B5670113

Date | Time : 29. Aug 2020 12:01:22 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

| Item            | Description                            | Qty | Unit Price            | Disc % | Amount   | 0% GST Amount | Amount incld GST |
|-----------------|----------------------------------------|-----|-----------------------|--------|----------|---------------|------------------|
| BOSUN           | REMOVE AND VACUUM SHATTERED GLASSES    | 1   | <del>650.00</del> 325 |        | 650.00   | 45.50         | 695.50           |
| BMU30R          | REMOVE & REPLACE EXHAUST SYSTEM.(N)    | 1   | <del>650.00</del> X   |        | 650.00   | 45.50         | 695.50           |
| BOSUN           | REMOVE AND RE-INSTALL TAILGATE SPOILER | 1   | <del>380.00</del> 280 |        | 380.00   | 26.60         | 406.60           |
| BP00R           | APPLY BODY UNDERSIDE COATING (N).      | 1   | <del>520.00</del> X   |        | 520.00   | 36.40         | 556.40           |
| Sum Labor       |                                        |     |                       |        | 19690.00 | 1,378.30      | 21,068.30        |
| RS-TMP3040L     | VPC 4PCS REAR SENSORS ?                | 1   | 320.00                |        | 320.00   | 22.40         | 342.40           |
| 33502-T7A-J01   | LAMP UNITR. ?                          | 1   | 482.40                | 25     | 361.80   | 25.33         | 387.13           |
| 33552-T7A-J01   | LAMP UNITL. can                        | 1   | 482.40                | 25     | 361.80   | 25.33         | 387.13           |
| 34150-T7A-J01   | LIGHT ASSY,R.LID can                   | 1   | 276.90                | 25     | 207.67   | 14.54         | 222.21           |
| 34155-T7A-J01   | LIGHT ASSYL.LID can                    | 1   | 276.90                | 25     | 207.67   | 14.54         | 222.21           |
| 68100-T7A-J20ZZ | TAIL GATE COMP st                      | 1   | 877.90                | 25     | 658.42   | 46.09         | 704.51           |
| 74440-T7A-003   | WEATHERSTRIPTAILGATE at                | 1   | 101.30                | 25     | 75.97    | 5.32          | 81.29            |
| 74800-T7A-J02   | LOCK ASSYTAILGATE ?                    | 1   | 86.20                 | 25     | 64.65    | 4.53          | 69.18            |
| 84431-T7A-J01ZA | LINING ASSYTAILGATE de                 | 1   | 139.60                | 25     | 104.70   | 7.33          | 112.03           |
| 75722-T7W-A01   | EMBLEMRR. ne                           | 1   | 14.60                 | 25     | 10.95    | 0.77          | 11.72            |
| 33505-T7A-J01   | REFLECTOR ASSYR.RR. ?                  | 1   | 170.80                | 25     | 128.10   | 8.97          | 137.07           |
| 33555-T7A-J01   | REFLECTOR ASSYL.RR. ?                  | 1   | 170.80                | 25     | 128.10   | 8.97          | 137.07           |
| 04717-T7A-000ZZ | FACER.RR.BUMPER CORNER ?               | 1   | 96.50                 | 25     | 72.37    | 5.07          | 77.44            |
| 04718-T7A-000ZZ | FACEL.RR.BUMPER CORNER de              | 1   | 96.50                 | 25     | 72.37    | 5.07          | 77.44            |
| 71593-T7A-000   | SPACER,R.RR.BUMPER SIDE ne             | 1   | 17.30                 | 25     | 12.97    | 0.91          | 13.88            |
| 71598-T7A-000   | SPACER,L.RR.BUMPER SIDE ne             | 1   | 17.30                 | 25     | 12.97    | 0.91          | 13.88            |
| 91505-TM8-003   | CLIP,BUMPER ne                         | 8   | 2.30                  | 25     | 13.80    | 0.97          | 14.77            |
| 66100-T7A-300ZZ | PANEL COMPRR. st                       | 1   | 382.70                | 25     | 287.02   | 20.09         | 307.11           |
| 84640-T7A-J01ZA | LINING ASSYRR.PANEL de                 | 1   | 45.00                 | 25     | 33.75    | 2.36          | 36.11            |
| 04655-T7A-310ZZ | PANEL SET,RR.FLOOR repair              | 1   | 693.00                | 25     | 519.75   | 36.38         | 556.13           |
| 72841-SH3-315   | OILSHEET X                             | 3   | 41.70                 | 25     | 93.82    | 6.57          | 100.39           |
| 73214-T7J-H01   | RUBBER CR.WINDSHIELD DAMPER ne         | 1   | 19.30                 | 25     | 14.47    | 1.01          | 15.48            |
| 73226-SZW-000   | DAMPERSTD 5X5 ne                       | 1   | 8.70                  | 25     | 6.52     | 0.46          | 6.98             |

Printed on 29/8/2020 12:12:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

# HONDA

## KAH MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : GOH GUO-HUA  
464 EAST COAST ROAD

SINGAPORE 429037

Registration No : SMD1081J

Chassis No : JHMRU1830JX200113

Model : HRV LX-SIN CVT YM 2018

Owner's Name : GOH GUO-HUA

Ins Policy No. :

Date of Accident : 28/8/2020

Document No. : SQT20002743

Page 3

Date : 29. Aug 2020

Customer No. : \*\*\*\*\*425E

Svc Advisor :

Engine No : L15B5670113

Date | Time : 29. Aug 2020 12:01:22 PM

Surveyor Name :

Survey Date :

Authorisation Date :

| Item          | Description                             | Qty | Unit Price | Disc % | Amount  | 0% GST Amount | Amount incld GST |
|---------------|-----------------------------------------|-----|------------|--------|---------|---------------|------------------|
| 73254-T7J-H01 | RUBBER CL.WINDSHIELD DAMPER <i>re -</i> | 1   | 19.30      | 25     | 14.47   | 1.01          | 15.48            |
| 76711-T6A-003 | CAPPIVOT <i>re -</i>                    | 1   | 5.00       | 25     | 3.75    | 0.26          | 4.01             |
| 91501-S70-003 | FASTENER BW/SHIELD <i>re -</i>          | 4   | 5.30       | 25     | 15.90   | 1.11          | 17.01            |
| 91502-S70-003 | FASTENER B <i>re -</i>                  | 2   | 5.30       | 25     | 7.95    | 0.56          | 8.51             |
| 91536-SS0-J01 | FASTENER AW/SHIELD <i>re -</i>          | 2   | 3.80       | 25     | 5.70    | 0.40          | 6.10             |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) <i>re -</i>      | 2   | 60.00      |        | 120.00  | 8.40          | 128.40           |
| 73211-T7A-N71 | GLASS SETRR.WINDSHIELD <i>bo -</i>      | 1   | 739.80     | 25     | 554.85  | 38.84         | 593.69           |
| Sum Item      |                                         |     |            |        | 4492.26 | 314.50        | 4,806.76         |

BO-VK-ASTRO-RWS SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREENSUPP

1 300.00 300.00 21.00 321.00

Sum Ext. Service 300.00 21.00 321.00

Survey By

Date & Time

Excess

Status

Signature

25468.91

Total Amount 24,482.26 1,713.80 26,196.06

Total (Inclusive of GST) 26,196.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 29/8/2020 12:12:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 29/08/2020 12:00 |
| Date Of Accident           | 28/08/2020 12:50 |
| Exact Location Of Accident | AYE TOWARDS TUAS |
| Country/State of Loss      | SINGAPORE        |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SMD1081J             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | GOH GUO-HUA          |
| NRIC No                     | SXXXX425E            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-91014072 |
| Alternative Phone No        | OFFICE-91014072      |

#### Vehicle Particulars

|              |              |
|--------------|--------------|
| Manufacturer | HONDA        |
| Model        | HR-V-1.5 (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

#### Insurance Company

|                           |                                           |
|---------------------------|-------------------------------------------|
| Name of Insurance Company | DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD |
|---------------------------|-------------------------------------------|

|                  |               |
|------------------|---------------|
| Type Of Coverage | COMPREHENSIVE |
|------------------|---------------|

|              |    |
|--------------|----|
| Fleet Policy | NO |
|--------------|----|

|               |  |
|---------------|--|
| Policy Number |  |
|---------------|--|

|                   |  |
|-------------------|--|
| Cover Note Number |  |
|-------------------|--|

#### Driver

|                |             |
|----------------|-------------|
| Name of Driver | GOH GUO-HUA |
|----------------|-------------|

|         |           |
|---------|-----------|
| NRIC No | SXXXX425E |
|---------|-----------|

|               |            |
|---------------|------------|
| Date Of Birth | 03/07/1980 |
|---------------|------------|

|            |        |
|------------|--------|
| Occupation | INDOOR |
|------------|--------|

|                      |            |
|----------------------|------------|
| Date Of Driving Pass | 25/04/2001 |
|----------------------|------------|

|                    |                       |
|--------------------|-----------------------|
| Driving Experience | 19 YEARS AND 4 MONTHS |
|--------------------|-----------------------|

|        |      |
|--------|------|
| Gender | MALE |
|--------|------|

|               |                      |
|---------------|----------------------|
| Mobile Number | (LOCAL) +65-91014072 |
|---------------|----------------------|

|            |  |
|------------|--|
| Fax Number |  |
|------------|--|

|                |                 |
|----------------|-----------------|
| Contact Number | OFFICE-91014072 |
|----------------|-----------------|

|               |         |
|---------------|---------|
| Email Address | NOEMAIL |
|---------------|---------|

Address

20 KAY POH ROAD #10-05 SINGAPORE 248969

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

REFER

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN8523K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category GOODS VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

Vehicle Number: \_\_\_\_\_

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time: \_\_\_\_\_


Driver's Signature  
(if driver is not the policyholder)  
Date & Time: \_\_\_\_\_



Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

Vehicle Number: \_\_\_\_\_

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. I was traveling along AYE towards Tuas. Heavy traffic. The front vehicle slow down and stop. I follow to slow down and stop. Vehicle B didn't stop in time and hit onto my vehicle A. My vehicle A rear portion was badly damaged.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

1008

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                |                |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID:      | 425E           |

|                               |                   |
|-------------------------------|-------------------|
| Vehicle No.:                  | SMD1081J          |
| Vehicle to be Exported:       | No                |
| Intended Deregistration Date: | 31 Aug 2020       |
| Vehicle Make:                 | HONDA             |
| Vehicle Model:                | HRV 1.5 LX CVT    |
| Primary Colour:               | Black             |
| Manufacturing Year:           | 2018              |
| Engine No.:                   | L15B5670113       |
| Chassis No.:                  | JHMRU1830JX200113 |
| Maximum Power Output:         | 96.0 kW (128 bhp) |
| Open Market Value:            | \$21,733.00       |
| Original Registration Date:   | 01 Aug 2018       |
| First Registration Date:      | 01 Aug 2018       |
| Transfer Count:               | 0                 |
| Actual ARF Paid:              | \$22,427.00       |

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 31 Jul 2028 |
| PARF Rebate Amount:           | \$16,820.00 |

|                      |                                      |
|----------------------|--------------------------------------|
| COE Expiry Date:     | 31 Jul 2028                          |
| COE Category:        | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):   | 10                                   |
| QP Paid:             | \$32,699.00                          |
| COE Rebate Amount:   | \$25,886.00                          |
| Total Rebate Amount: | \$42,706.00                          |

The information contained herein is correct as at 31 Aug 2020

OK

Merimen e-Claims

Used 2018 Honda HR-V 1.5A LX

PARF/CO

art.com/used\_cars/info.php?ID=922950&DL=2642

## Honda HR-V 1.5A LX

Overview

Financial

Accessories

Similar

Research

Photos

Map

AUTOMOBILE

CARTIMES

An Award-Winning Premier Automotive House



Price \$81,800

Depreciation ⓘ \$8,790 /yr  
View models with similar depre

Reg Date 25-Sep-2018  
(8yrs 24days COE left)

Mileage 18,688 km (9.7k /yr)

Manufactured ⓘ 2018

Road Tax ⓘ \$682 /yr

Transmission Auto

Dereg Value ⓘ \$40,690 as of today (change)

OMV ⓘ \$21,245

COE ⓘ \$30,209

ARF ⓘ \$21,743

Engine Cap 1,496 cc

Power 96.0 kW (128 bhp)

Curb Weight ⓘ 1,190 kg

No. of Owners ⓘ 1

Type of Vehicle SUV

### Features

1.5L I-VTEC Engine, 128 BHP, CVT Automatic Transmission, ABS, Airbags, Electronic Parking Brake, Cruise Control. View specs of the Honda HR-V (2015)