

ASS. REC. BY:

REF:

CS / AGI 2000 9188 / Avf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKA1429E Yr Regn: 2011 / Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C. 1598Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 138520 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MROS3REE104111145Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R16R: 195/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Leao

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. 29/8/20 D.O.I. 01/09/20Survey held at Hua MengDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Budget Direct..</u>
	<u>MV: 15K</u>
	<u>PV: 9.6K</u>
	<u>Nett: 3.4K</u>
<u>11/10/20</u>	<u>Adrian confirmed LS \$4000 (Red 4761.70, 54%)</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 15/10/20 - TypistDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

3 + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format: TPLump Sum / L.P.J. LS \$4000

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 173J

Vehicle Details

Vehicle No.: SKA1429E
Vehicle to be Exported: No
Intended Deregistration Date: 01 Sep 2020
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Blue
Manufacturing Year: 2011
Engine No.: 1ZR063636
Chassis No.: MR053REE104111145
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$15,510.00
Original Registration Date: 25 Jan 2011
First Registration Date: 25 Jan 2011
Transfer Count: 2
Actual ARF Paid: \$15,510.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Jan 2021
PARF Rebate Amount: \$7,755.00

Intended COE Rebate Details

COE Expiry Date: 24 Jan 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$46,129.00
COE Rebate Amount: \$1,822.00
Total Rebate Amount: \$9,577.00

The information contained herein is correct as at 01 Sep 2020

OK

Singapore Reckless Drivers Part VIII

COE Bidding – 1st Round of August 2020

Unusual or Rare Cars - Part 2

[Advanced Search](#)

Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A



Clear All

[Add all to Shortlist](#)[Add to Shortlist](#)[Add to Shortlist](#)[Add to Shortlist](#)

Use search bar above to search to compare.

[Back to search result](#)

CAR DETAILS

Price	\$16,400	\$19,800	\$17,900	-
Instalment	\$1,942	\$2,014	\$1,423	-
Registration Date	08-Mar-2011	01-Apr-2011	13-Jun-2011	-
Manufactured	2011	2011	2011	-
Mileage	138,600 km	141,464 km	76,133 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,598 cc	1,598 cc	1,598 cc	-
Road Tax	\$742 /yr	\$742 /yr	\$742 /yr	-
Power	90.0 kW (120 bhp)	90.0 kW (120 bhp)	90.0 kW (120 bhp)	-
Curb Weight	1,195 kg	1,195 kg	1,195 kg	-
Features	A1 Condition, No Repair Required.	-	Facelift Model. Well Maintained, Just Done Auto Transmission Oil Change And Servicing. 4 Pcs Of Brand New Tyre. New Interior Carpet. Clean And Neat	-
Accessories	Face Lift Model Dual Vvti, Loan With COE Renewal Available.	-	Genuine Low Mileage With Records Of Mileage From Previous Owner. Immediate Transfer. Good Choice To Buy And Wait Low Coe Renewal Rate.	-
Description	1 To 1 Trade With Used Car/Scrap Car/COE Car.	Excellence Condition, Regular Maintained, Low Mileage, Smooth Engine, Easy To Maintain Unit, Sports Rims, Leather Seats, Android Player Come With Bluetooth, Reverse Camera Gps Etc, No Repair Needed, Good For Future Coe Renewal.	Dual Vvti Facelift Model. Loan And Trade In Available.	-
COE	\$42,999	\$42,999	\$47,604	-
OMV	\$15,510	\$15,510	\$15,263	-
ARF	\$15,510	\$15,510	\$15,263	-
Depreciation	\$16,870 /yr	\$20,840 /yr	\$13,200 /yr	-
No. of Owners	2	4	3	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car, Direct Owner Sale	PARF Car	PARF Car, Direct Owner Sale, Low Mileage Car	-
Availability	Available	Available	Available	-
SELLER INFORMATION				
Seller	Direct Owner	Corsica Trading	Direct Owner	-
Address	-	-	-	-

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2020 14:36
Date Of Accident	29/08/2020 11:15
Exact Location Of Accident	PIE TWDS CHANGI BEFORE LORNIE RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA1429E
Insured/Policyholder	
Name Of Registered Owner	KS LEASING
Co Reg No	5XXXX173J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97908632
Alternative Phone No	OFFICE-97908632

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5116909182
Cover Note Number	

Driver

Name of Driver	OO ER MENG
NRIC No	SXXXX453I
Date Of Birth	09/02/1959
Occupation	OUTDOOR
Date Of Driving Pass	29/06/1989
Driving Experience	31 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91819657
Fax Number	
Contact Number	OFFICE-91819657
Email Address	NOEMAIL

Address	BLK 642 JURONG WEST STREET 61 #02-62
Postcode	640642
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4303U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TANG WEI PING
NRIC/Passport Number	SXXXX851B
Contact Number	94879904
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	OO ER MENG
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SKA1429E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN



Journal of Management Education 30(6)

W. J. H. W. W. W.

7-10-68

7-10-68

7-10-68

5

A. S. K. 96

I was driving along the track (hang) before Linné Rd. after Speed corner.

in time out of sudden vehicle B hit onto rear portion of my
vehicle

1. The above foregoing particulars are true in every respect.



Reporting Centre Personnel Signature
Name:
NRIC/Fin No: