



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20009242/Acf3q2 Date: 25/01/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 76T	Veh. Inspected	SFG 4885D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10007161	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	01/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 250	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WDD2043472F873999	Colour	WHITE	
Odometer	135773 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	MICHELIN	6 mm	
L/H Front Tyre	225/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/08/2020	Inspection Date	01/09/2020	
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	