

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS	NS/INC20009278/T1qf3s2		
73 BRAS BASAH ROAI #05-01 NTUC TRADE U 189556	Date: 07	7-09-2020			
		Code: IN	C4		
1. Policy Particulars :- THIRD PARTY CLAIM					
Insured Veh.	GBK 3808K	Veh. Insp	ected	SHA 1206S	
Policy No.		Coverage	(\$)	0.00	
Claim No.	MT/1101860-002	Excess (\$	5)	0.00	
Assign From		Assign Da	ate	31/08/2020	
2. Vehicle Particulars & Condition					
Make & Model	HYUNDAI IONIQ	c.c		1580	
Engine No.	HIDDEN	Year of Re	eg.	2018	
Chassis No.	KMHC851CVKU106493	Colour		BLUE	
Odometer	222708	Steering		IN ORDER	
Brakes	IN ORDER	Modification		SPORTS RIM	
General	GOOD				
3. Conditions of Tyres					
	Size	Make		Balance	
R/H Front Tyre	195/65 R15	DAVANTI		6 mm	
L/H Front Tyre	195/65 R15	DAVANTI		6 mm	
R/H Rear Tyre	195/65 R15	DAVANTI		6 mm	
L/H Rear Tyre	195/65 R15	DAVANTI		6 mm	
4. Description of Damages					
THE VEHICLE SUATAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5. General Information					
Accident Date	28/08/2020	Inspection	n Date	31/08/2020	
Survey held at	COMFORTDELGRO ENGINEER	DELGRO ENGINEERING PTE LTD			
	59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: