

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTU	C INCOME INSUF	RANCE CO-OPERATIVE LTD	Ref:	ef: NS/INC20009283/T1qf3s2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	17-09-2020 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJD 81B	т —	nspected	SHA 4762H	
	Policy No.	5100407855-02	Covera	age (\$)	0.00	
	Claim No.	MT/1102814-001	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	31/08/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2018	
	Chassis No.	KMHC851CVJU103526	Coloui	ſ	BLUE	
	Odometer	335245	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	DAVAN	TI	6 mm	
	L/H Front Tyre	195/65 R15	DAVANTI		6 mm	
	R/H Rear Tyre	195/65 R15	DAVAN	TI	6 mm	
	L/H Rear Tyre	195/65 R15	DAVAN	TI	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/08/2020	Inspec	tion Date	31/08/2020	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						

Estimate Days of Repair

2 Working Days