

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJS3256R

at Workshop m/s

m-126

of

Insured:

SHC14707

Policy No.

Claims No.

D20003401MFSH

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

2712

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

806

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJS3256R Yr Regn: 8, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

41

Make:

Toyota conolle AHIS.C 1598

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

196065

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR0532EE10640451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rip / STD A/Rim or

Tyre Size:

F:

R:

195/65-R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/8/20

D.O.I.

7/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Cor 10-8-2024 LTA # 11488

10/9/20 Confirmed N/S # 2100 w.e AH meny (Red \$1249.80, 37%)

10/09/20@11.46am revised to Vic by email.

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

4

10/09 Typist

☐

: Final Report

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

)

TOTAL

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum + L.B. (\$

2100

)



MOTOR SERVICES

Reg No: 26925200B

Blk 9005, Tampines Street 93, #01-252,
Tampines Industrial park A, Singapore 528839
Phone no: 67840077 Fax no: 67883025
Email: Mtechmotorservices@Gmail.com

not Authorized
2/5 @ 2100
Hday.
7/9/20

Customer :

SJS3256R (Jason),
Singapore -
Phone no: 90309798

Quotation No: Quo 33	Dated: September 7, 2020
Make and Model : Toyota Altis	Mode/Terms Of Payment: Due upon receipt
Mileage :	Chassis/ Car Plate No : MR053ZEE106150451 / SJS3256R

S.No	Item	Description	Quantity	Unit	Rate(SGD)	Amount (SGD)
1	Rear bumper cover	0/5	1	522.23	522.23	522.23
2	Rear bumper side brackets	0/5	1		58.00	58.00
3	Rear bumper sponge	Torn	1		168.00	168.00
4	Rear Bumper Arm Sub Assy	n1	1		84.00	84.00
5	Rear bumper reflector	*F	1		49.80	49.80
6	Rear bumper clip	one	6	25%	4.00	24.00
7	Rear Panel Inner Trim Garnish	2w1	1		268.00	268.00
8	Rear panel inner trim garnish clips	n1	5		4.00	20.00
9	Real end panel	DD	1		559.00	559.00
10	Labour (General)	-Panel Beating	1		650.00	650.00
11	Re-Spraying Work (Exterior only)	*Accident affected parts*	1		600.00	600.00
12	Reverse sensor	s.n	1	Set	300.00	300.00
Sub Total (SGD)						3,349.80
Total (SGD)						3,349.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9 - 1649.03
25%
9. 1236.77
s.n 200.00
2 - 1200.00
2636.77
2109

Amount in words :
Three Thousand Three Hundred Forty Nine and Eighty cents Singapore Dollar (SGD) Only

Declaration:

We declare that this Quotation shows the actual price of the goods described and that all particulars are true and correct.

* Computer Generated Proforma Invoice no Sign Required

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	560E
Vehicle Details	
Vehicle No.:	SJS3256R
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Sep 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	3ZZ4914963
Chassis No.:	MR053ZEE106150451
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	11 Aug 2009
First Registration Date:	11 Aug 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,664.00
COE Rebate Amount:	\$11,486.00
Total Rebate Amount:	\$11,486.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Sep 2020

OK