ASSIGNMENT

From: Date:

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SML1974R Yr Regn: 2019 May.

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mit Outlender cc 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp Reading: 41965 T/Radio: Insured / Std / NI / NA

Eng/No

C/No: GF7W0601471.

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 225/55R18.
R: 225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / (TOYO) / YOKO or

Front			Rear		
R/Bal.	06	mm	R/Bal.	06	mm
L/Bal.	06	mm	L/Bal.	06	mm
D.O.A.			D.O.I.	03/09/20	

Survey held at: STK.

Des. of Damages : Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP AlG.
	MV :
	PV :
	Nett :

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($
☐ : Interview ($
☐ : Tech. Inv. ($
☐ : Weekend ($

Survey Fee:

Transportation

___$ + PS ___ $

Photos

Other

Total

Report Format :

Lump Sum / ...