

ASS. REC. BY:

REF: CS/MSG20009377/Kqf3

Special Instruction:

Surveyor: KENNETH ASSIGNMENT (Office)From (Person): Christina Wong of MSIG Date/Time: 03 Sep 2020 10:47

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: YM 6871Z Insured: XE 2535Aat Workshop m/s BIFROST Tel: 9641 2187of Blk 9 Sector C, #01-42 Sin Ming Industrial EstatePolicy No: 30001320103 Claim No: 247143

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/08/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 3-9-20 10.56A.M Person Contacted: HEAH Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	INSPECTION:160 SIN MING AUTOCITY #01-13
	YM 6871Z- CV1/VAL20000233/Ut DOA :27/08/2019
	XE 2535A- ☒
27-11-20 4.40P.M	SPEAKE TO MS LEE WAITING FOR LIABILITY CLEAR AND SURVEY.
29-01-21 9.23A.M	CHECK V REGINA