



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20009423/Kyf3e2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 24-09-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLJ 9791X	<b>Veh. Inspected</b>	SML 7837P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10007200	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JUSTIN WONG	<b>Assign Date</b>	04/09/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA VOXY (A)	<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	ZWR800374284	<b>Colour</b>	METALLIC BLACK
<b>Odometer</b>	104934	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	GOODYEAR	8 mm
<b>L/H Front Tyre</b>	195/65 R15	GOODYEAR	8 mm
<b>R/H Rear Tyre</b>	195/65 R15	YOKOHAMA	7 mm
<b>L/H Rear Tyre</b>	195/65 R15	YOKOHAMA	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/09/2020	<b>Inspection Date</b>	04/09/2020
<b>Survey held at</b>	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.		

### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>5 Working Days</b>
--	-----------------------