

China-CPFR 0317

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 03.09.2020
Time: 15:12:48
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305420531
REGN NO : SHD4794A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 26.06.2019
DATE/TIME IN : 03.09.2020 12:15
ACCIDENT DATE : 02.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0104-2288-G	BEAM-RR BUMPER	1	459.40 20.00 367.52 ?Xnn
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25 20.00 361.00 de
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00 20.00 17.60 Xnn
0004	04-01-0104-1150-A	PROTECTOR MAT	1	50.00 2.00- 50.00 de
0005	FNPS	NO PLATE(S)	1 N	25.00 0.20 25.00 cna
0006	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50 20.00 161.20 Xnn 453.60

SUB-TOTAL : 982.32

JOB NATURE

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000	PB	PANEL BEATING		400.00 320
0001	SP	SPRAYPAINT CHARGE		300.00 200
0002	L	REMOVE/REFIX REVERSE SENSOR		80.00 30
0003	17-01	CHECK ALL LIGHTING		50.00 Xnn 750
0004	20-05	RENEW ADVERTISEMENT STICKER-		200.00 de

Taughtin 7741 5749
WP' 3/9/20 C 4pm
2 days
P/P Resurvey after repair
taughtin 11kanto wnn
453.60
750
1203.60
2 days
#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____