

ASS REC BY: Tan

REF:

CTI
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Sal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Lucien

Vehicle: IN / OUT

Veh No: SHC111C Yr Regn: 2017 FebType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Long c.c. 1580Colour: Yellow A.C.: Insured / Std / NI / NASp. Reading: 393227 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: U11ML 85 / CVH4022729Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: N N

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 3/9/20Survey held at Compass Road

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/tp or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time _____ Action/Instruction _____

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)

S + RS \$ _____

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

215 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9735
Workshops
59 Loyal Drive Singapore 508989 24 Serangoon Road Singapore 159138
383 Sin Ming Drive Singapore 575717 7 Bonge Road Singapore 159138
45 Pandan Road Singapore 121088 501 Matheson Industrial Park A Singapore 768220

Date/Time: 03.09.2020 13:38

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO.: 305420387

COMER
CITYCAB PTE LTD
7010070
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188
(R) (O)
(P)


REGN NO. SHC 111C	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2..... F
MODEL IONIQ	DATE/TIME IN 03.09.2020 12:00
YR OF MANU. 24.02.2017	TARGET DATE
CHASSIS CODE RMHC851CVHU022729	COMPLETION DATE/TIME

OUNT CARD NO.

JOB DESCRIPTION

Accident Date: 03.09.2020
NATURE: 3P 03.09.2020

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

SHC 111C JU CHINA LKK

Exit Pass

Vehicle No. SHC 111C

Signature/Date

Signature/Date

Name of Service Advisor

Date

Turnover to Service Reception upon collection

To be kept by Service Advisor