

Chma-Lyrum (Ju)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 03.09.2020

Time: 13:43:16

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305420387
REGN NO : SHC 111C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ
DATE OF REGN : 24.02.2017
DATE/TIME IN : 03.09.2020 12:00
ACCIDENT DATE : 03.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	del
0002 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	451.25	20.00	361.00	ent
0003 04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	2.00-	50.00	net
0004 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60	net

SUB-TOTAL : 796.12

JOB NATURE

0000 PB	PANEL BEATING	400.00	320
0001 SP	SPRAYPAINT CHARGE	500.00	400
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 980.00

TOTAL : 1,776.12

MVA NAME & SIGNATURE
DATE: 3/9/20

SURVEYOR NAME & SIGNATURE
DATE: 3/9/20 @ 4pm

AUTHORISED : YES / NO

Tanfer 97495749
wp' 3/9/20 @ 4pm
2 days
1/3 Repair after repair
tanfer libeatoon.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature