Our Ref		SHC 1110
Your Ref	:	
Date	: _11-Sep-2020	
CHINA TA	AIPING INSURANCE	CO LTD
3 ANSON	ROAD	
#16-00 S	PRINGLEAF TOWE	R
SINGAPO	RE 079909	
Attn : Mo	otor Claims Depa	rtment
Dear Sir		
ACCIDE	NT INVOLVING O	UR TAXI
AND OTH	IER	
	ne authorised repair	
SHC 11	1C which was invo	Ived in the
The vehic	le owner and the tax	di driver co

COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

Mainline +65 6383 6280 Facsimilie +65 6280 9755

www.cdge.com.sg

ompany Registration No: 199506048W

Workshops

205 Braddell Road Singapore 579701

Loyang 59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

CDGE Taxi Claims Dept 59 Loyang Drive 4th Flr Singapore 508969 205 Braddell Road Singapore 579701

Attn : Motor Claims Department	WITHOUT PREJUDICE	Co
Dear Sir		
ACCIDENT INVOLVING OUR TAXI AND OTHER	SHC 111C YOUR INSURED ON	3 Sep 2020
We are the authorised repair workshop for SHC 111C which was involved in the The vehicle owner and the taxi driver count them in presenting their claims against the from the damage to the vehicle.	captioned accident with your insuncerned have requested and author	red vehicle. orized us to assist
As the accident was caused by the negli we are submitting these claims for your	igent act of your insured driving: consideration on behalf of the clai	GBK 796E mants.
TAXI OWNER'S CLAIM 1 Cost of Repair 2 3 days Loss of Rental @ 3 Survey Report Fees (Surveyed 4 LTA Search Fees 5 GIA / Police Report Fees 6 Towing / Medical / Transporation F HIRER'S CLAIM 7 3 days Loss of Income @	d by M/s LKK)	\$ 240.00
We enclose herewith the following docu	uments to support the claims: -	

1C /WT/CK(st)

Original repair bill:

b) LTA search slip/s of:

GBK 796E

GIA / Police report/s of: c)

SHC 111C

Letter of authority from owner / hirer / operator

) Photocopies of Accident Scene Photos

() Certificate of Insurance (x) Rental Rate letter

()PIR

(x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as

soon as possible. Please note that it is a condition of any settlement reached that it shall be without prejudice

to any personal injury claim (if any) of the taxi driver.

Yours faithfully Catherine Koh

CDGE Claims Department

Tel: 6214 8733 Fax: 6214 1843 Email: catherinekoh@cdge.com.sg

This is a computer generated letter. No signature is required.

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

Hyundai Ioniq SHC111C , GBK796E

ON 03-Sep-20 09:10

ALONG

PUNGGOL FIELD X PUNGGOL ROAD

I / We

TAY YONG HOCK

(Hirer) NRIC No .:

SXXXX712C

and/or

(Relief) NRIC No.: SXXXX712C

Taxi Number

SHC111C

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

03-Sep-2020

Name of Hirer

TAY YONG HOCK

Hirer NRIC

SXXXX712C

Signature:



Address

326A SUMANG WALK #21-994

821326

Contact No.

84285955



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshons

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768

COMPANY REG. NO.: 199506048W

Page: 1

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE 079909

CONTACT NO: 62222366

VEHCLE NO SHC 111C

NO/DATE 91522986 07.09.2020

MAKE HYUNDAI JOB NO. 305420387

MODEL IONIO ODOMETER READING

DATE OF REG 24.02.2017

CHASSIS CODE KMHC851CVHU022729 JOB TYPE

Description: 3P 03.09.2020

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt Add GST @ 7.000

Total Invoice amount

1,337.50

Issued by : KATHERINETAN 07.09.2020 15:23:42 Repair Type : CFSO/57/57 Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CC20090025

Date: 07 September 2020



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

03/09/2020 @ 09:10 hrs

ALONG

PUNGGOL FIELD X PUNGGOL ROAD

INVOLVING

GBK796E

We refer to the above-mentioned accident and wish to inform that CityCab Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC0111C (the "Taxi"). The Taxi was hired to TAY YONG HOCK IC NO SXXXX712C a registered hirer-operator of CityCab Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.19 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Manager, Fleet Safety

This is a computer generated letter. No signature is required.

A. S. C.	apparamenta seconda sebelita caracteris de Antologia, casalogia de Antologia de Ant		7 (
To the state of th				HOLIBS OPERATED (TIME)	ATED (TIME)			
			TOWELEAGE	וויייייייייייייייייייייייייייייייייייי		DATE	NAME OF DRIVER	MILEAGE RE.
DATE	NAME OF DRIVER	MILEAGE READING	(KM)	FROM	10			
400000	大きていのり		3	200	ſ			
コペーシャカロ	こうさ	2	, !	1604	1			
oc. o. So Repair	Leyday	ī	3	35				
							and the second s	
The second secon								
			1					
			N. K.					
		\						
-								
The same of the sa							CONTRACTOR OF THE PROPERTY OF	Company of the Compan

1 1

. .

Enquire Vehicle Insurance Details

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

GBK796E

03 Sep 2020 / 09:10:00 Successful

C01

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

ОК