


PRS

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD:  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: MJE MOTOR  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: YN 8114H Yr Regn: 13 May/2015  
 Type: M.Car / M.Cycle / Bus / Van /  Corn / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
 Make: ISUZU NPR85UH5A 3.0 c.c. 2999  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 311702 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JAANPR85HF7100196 \*  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 1 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Tyre Size: F: 195/85R16 WESTLAKE  
 R: 205/85R16 HANKOOK  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  

<u>Front</u>	<u>Rear</u>
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>21-09-2020</u>

 Survey held at W/S 11:30  
 Des. of Damages: Frt /  Rea / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$500 - \$1000

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Filed?  
 Long Copy/MP/...

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Insp (\$ \_\_\_\_\_)  
 : Wash/End (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	