HEF: (53/AIG 2000 9489/E+f3 ASS. REC. BY: STEN ASSIGNMENT Dale: From: Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Estimated Cost: OD IT PY WS I TP RES I OD RES I EVA I INV I MY Toyola Plius Make: To Inspect Vehicle No: Insured / Std / NI / NA , A/C: at Workshop m/s T/Radio: Insured / Std / NI / NA Sp.Rending Eng/No: Insured: . C/No: Gen. Cond: Good / Fair / Poor / Burnt Claims No. Steering: Inforder / Jammed / Leaked / Burnt or Excess: Sum Insured: Inordo / Jammed / Leaked / Burnt or (Client's Record) Modi: NII / \$/RIm / STD A/RIm or Make of Veh: Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / N/S OIS Remark: The veh had commenced its TOYO I YOKO OF repair at the time of inspection. Front Roar Bal. or Market Value: R/Bal. R/Bal. Consistent?: Yes or No IDAC Accident Rport: UBal. UBal. mm Consistent?: Yes or No GIA / PR Seen: D.O.I. D.O.A. Res.: Yes or No days Est. Repairs: 3 Val.: Yes or No Lum Sum: O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN/OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction SUBMIT DAR REPORT Days Of Repair: : Prell. Report Survey Fee: Resurvey No. of Trip: : Final Report Transportation: Date/Time, File Return to? _S + RS, __SI Add Fee: : Site Insp (\$: Interview (\$ Tech. Inva (\$ Cithers. Per ormei: Weetend (\$ Lump Sun / LEJ: Ca TOTAL

MOTORCAR (Rear)

ASTROJERAC)

(1)Replace (2) 1 (2)Repail(4) (3)Check (5) (4)Not Consistent (IC)

ANE ZINIS

SMJ 1321K Vehicle No:

•••	4 4	(14)Unconfirmed (13)Not Working				
Rear Pe			-		17.	77
NAC	INC.	Item	COL	AV	7	73
1137	993626	Rear Number Plate	ar ann mainten			7-
1138	993627	Rear Number Plate Base	- A direction			
1139	993630	Rear Number Plate Garnish			-	
1140	993632	Rear Number Plate Lamp	-2525		,	
1141	992958.	Rear Bumper Rear Bumper Upper	DAL			
1142	993085	Rear Bumper Upper	र पन		>	es. 0-1
1143	993017	Rear Bumper Lower	141	V.		-
1144	993054	Rear Bumper Side	(W)		-	
1145	993103	Rear Bumper Tow Cover	, ,		7-	~ .
1146		Rear Bumper Clips	NL			
1147	1	Rear Bumper Bracket	77		,	
1148			LR	-16		
1149						
1150		Rear Bumper Beam		-17		
1151	993077	Rear Bumper Sponge				
1452		Rear Bumper Damper			_	
1153		Rear Bumper Protector			1	
		Rear Bumper Part Olde Colle	-			
1155		Rear Bumper Moulding			_	
1155	993044	Rear Bumper Reflector			_	
		Rear Bumper Lower Spoiler	100		4	_
		Reverse Sensor	UR		-	_
1159	993327	Rear End Panel				_
1460	993339	Rear End Panel Top Garnish	-		4	
		Rear End Panel Inner Trim			-	
		Boot Compartment Inner Trim		-		
		Rear LH Taillamp	-		-	_
1154		Rear LH Taillamp Garnish	4-	_	-	
		Rear LH Taillamp Panel	-	-	-	
		6 Rear RH Taillamp	-		-	7.75
116	99385	Rear RH Taillamp Garnish		-	-	
110	99385	A iricat fin I amamb Lanci	-	-+		
110	01.00300	4 Réar Apron Panel 5 Bootlid	+-	\dashv		-
		8 Bootlid Emblem		\dashv	-	
		6 Bootlid Handle	+	\rightarrow	-	-
117	2 00575	0 Bootlid Moulding		-		_
		6 Bootlid Reflector		-	-	
		2 Bootlid Lamp LH		-		
		9 Bootlid Lamp RH	_			-
		3 Bootlid Lock		-		
		77 Bootlid Rubber	_	\neg		
		32 Bootlid-Hinge	_	_		
		77 Bootlid Spoiler	7	1		
118		13 Tailgate	_		R	
118		28 Tailgate Emblem			**	
		13 Tailgate Outer Handle				-
118		10 Tailgate Moulding				
118		15 Tailgate Garnish				
118		48 Tailgate Reflector				
		19 Tailgate Lamp				Γ
		46 Tailgate Protector				
- 118		76 Tailgate Wiper Arm				
	9946	77 Tailgate Wiper Blade				
111		79 Tailgate Wiper Nozzle	.]			
111		55 Tailgate Wiper Motor			L	
		02 Tailgate Glass				
	94 9940	06 Tailgate Glass Rubber				
11	95 9940	04 Tailgate Glass Moulding				
	96 9940	707 Tailgate Glass Sealant				
	97 9940	Tailgate Lock			-	1
		551 Tailgate Rubber			-	
		511 Tailgate Hinge			1_	
12	200 994	594 Tailgate Damper	J_		الـ	.l
1.14	.00 774	774 Taligate Dalliper				l

	-	Vehicle No: ONI	1J/1		
	AC I	tem	CON		Qb
202 99	3784	pare Tyre Board			
2.03 99	4328 5	pare Tyre Panel			
	5065 5	pare Tyre			
	4326 5	Spare Tyre Lock Screw			
	3787 5	pare Tyre Cover			T_
207 99	5323	Friangle Breakdown Sign			T
		CD Changer Assy	-		T
209 99		Antenna			
210 99	0534	Centre Exhaust Pipe Assy	1	1	1
211 99	0532	Centre Exhaust Mounting	1	1	1
212 99	3364	Rear Exhaust Pipe	1	1	+-
		Rear Exhaust Chrome Pipe	-	+-	1-
		Rear Exhaust Mounting	1	1-	1-
		Rear Exhaust Heat Shield	1	+	+
		Rear LH Chassis Member	-	+	+
		Rear RH Chassis Member	-	+-	+-
		Kear LH Fender	-	1-	
		Rear LH Fender Protector	+	+	+-
		Rear LH Fender Inner Panel	+	1	-
		Rear LII Fender Inner Trim	1-	+-	1-
		Rear LII Fender Inner Garnish.	1	1	+
		Rear LH Fender Inner Shield .	-	+	-
		Rear LH Mudflap	+	+-	-
		Rear LII Wheel Rim	+-	1	-
		Rear LH Rim Cover	+-	-	+
		Rear LH Tyre	+-	1	+
		Rear RH Fender	+-	+	+
		Rear RH Fender Protector	+-	+	+
		Rear RH Fender Inner Panel	+-	+	+
		Rear RII Fender Inner Trim	+-	+	-
		Rear RH Fender Inner Garnish	1	1	+
		Rear RH Fender Inner Shield	1-	-	-
		Rear RH Mudflap	-	1	1
		Rear RH Wheel Rim	1	1	1
		Rear RH Rim Cover	+-	+	1
		Rear RH Tyre	+-	+	-
1238 9	95162	Rear Fender Extension Panel LI	1	+	1
1239 9	93401	Rear Fender Extension Panel RJ		+	-
		Rear Fender Inner Top Garnish	+-	+	-
		Rear Fender 1/4 Glass		+	+
1242 9	93452	Rear Fender 1/4 Glass Rubber	+	1	1
1243 9	93453	Rear Fender 1/4 Glass Scalant	1	_	1
		Rear Windscreen Glass	-	1	-
		Rear Windscreen Rubber	-	1	1
		Rear Windscreen Moulding	-	+	+
		Rear Windscreen Sealant	1	+	+
		Third Brake Light		+	1
		Rear Fender Air Grille	_	+	1
		Fuel Lid	-	+	-
		Fuel Neck	-	-	-
		Fuel Tank		+	-
		Fuel Tank Bracket	-	+	+
1254	002101	Fuel Tank Float	-	-+	-
		Sticker	+-	+	+
2/1/7/08	990247	GIICKEI	-	-	+
				+	+
 			-+-	+	+
		· · · · · · · · · · · · · · · · · · ·		+	-
		·			+
				+	
		-	- -	+	-
			-	<u>-</u>	-
					-

4 repar days