

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CAS GARAGE PTE LTD Ref: CS/TP20009512/Atf3e2

| |1 KAKI BUKIT AVENUE 6 #02-22 AUTOBAY @ KAKI Date: 02-11-2020

BUKIT SINGAPORE 417883 417883

ON BEHALF OF CHANDRASEKARAN S/O Code: TP516

		Policy Particular	rs :- THIRD PARTY CLA	IM
	Insured Veh.		Veh. Inspected	SGA 9690K
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	03/09/2020
2.		Vehicle Par	rticulars & Condition	
	Make & Model	HYUNDAI ELANTRA	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KMHD841CMJU592594	Colour	GOLD
	Odometer	39135	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Cond	litions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	GOODYEAR	6 mm
	L/H Front Tyre	225/45 R17	GOODYEAR	6 mm
	R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm
	L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm
1.		Descrip	otion of Damages	
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE D	ETAILS.		
5.		Gene	ral Information	
	Accident Date	01/09/2020	Inspection Date	03/09/2020
	Survey held at	CAS GARAGE PTE LTD		
		NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		
5a.			Remarks	
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days			