

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305421224
Date : 07092020
Time of Fax: _____

Via Fax : Email
Your Insured: SDE 8318H
Date of Acc : 07092020

Attn: Motor Claims Department

Dear Sirs

Argbia

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 3317B

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

◆ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} Fax no. 6546 8156
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
◆ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	
◆ Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

for Vice President
Crash Repairs & Claims Recovery

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Ag Asia

Date: 07.09.2020

Time: 14:29:00

Page: 1

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305421224
 REGN NO : SHD3317B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 08.07.2016
 DATE/TIME IN : 07.09.2020 12:15
 ACCIDENT DATE : 07.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0573-A	FRT FENDER RH	1	663.00	20.00	530.40
0002 04-01-0103-0592-G	FRT DOOR RH	1	2,256.40	20.00	1,805.12
0003 04-01-0103-0595-G	REAR DOOR RH	1	2,201.10	20.00	1,760.88
0004 04-01-0103-0658-G	FRT RH & REAR RH WHEEL CAP	2	214.20	20.00	171.36
0005 28-01-0103-0003-A	Frt Door ComfortDelGro RH	1	75.00	2.00	75.00
0006 28-01-9999-2023-A	Rear Door APPS Sticker RH	1	80.00	0.20	80.00

SUB-TOTAL : 4,422.76

JOB NATURE

0000 20-05	Frt Fender Adv.Sticker RH	100.00
0001 20-05	Both RH Doors Adv.Sticker	200.00
0002 20-05	Rear Fender Adv.Sticker RH	20.00
0003 PB	PANEL BEATING-Rear Fender RH etc	600.00
0004 SP	SPRAYPAINT-Rocker Panel Garnish RH	1250.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.09.2020

Time: 14:29:00

Page: 2

Arg Asia

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305421224
REGN NO : SHD3317B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.07.2016
DATE/TIME IN : 07.09.2020 12:1
ACCIDENT DATE : 07.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0005 20-00 TUFF COAT ON AFFECTED PARTS. 100.00

0006 L TRANSFER OF DOORS 240.00

SUB-TOTAL : 2,510.00

TOTAL : 6,932.76

Limfs

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :