



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : EQ Insurance Company Ltd
 5 Maxwell Road
 #17-00 Tower Block, MND Complex
 Singapore 069110

Estimate No: ES2000083
 Date: 08 Sep 2020

ATTN: Motor Claim Department

Not Authorized

Policy No: SDH9211J
 Veh Reg No: VOLVO S90 T5
 Make/Model: MOMENTUM
 Chassis No: YV1PS10BDH1006759
 Engine No: B4204T231801480
 Reg. Date: 28/12/2016

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 25/08/2020
 TP Veh Reg No: SJD5848Z

*11 Sep 8
 Repair After Paint
 2 days*

Estimate Repair Cost to Vehicle No :SDH9211J

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 FRONT WHEEL RIM - RH	1,250.00	1 PC	1,250.00	
2 FRONT TYRE - RH	450.00	1 PC	450.00	
			1,700.00	1,700.00
Spare Parts				
3 FRONT BUMPER	2,250.00	1 PC	2,250.00	
4 FRONT BUMPER PARKING SENSOR	368.50	1 PC	368.50	
5 FRONT BUMPER SIDE RETAINER - LH	90.80	1 PC	90.80	
6 FRONT BUMPER SIDE RETAINER - RH	90.80	1 PC	90.80	
7 FRONT BUMPER CLIPS	60.00	1 SET	60.00	
8 HEAD LAMP - RH	3,250.10	1 PC	3,250.10	
9 FRONT FENDER - RH	885.50	1 PC	885.50	
10 FRONT FENDER SPLASH SHIELD - RH	285.90	1 PC	285.90	
11 FRONT FENDER SPLASH SHIELD CLIP	80.00	1 SET	80.00	
			7,361.60	7,361.60
Labour				
12 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,000.00	1 JOB	1,000.00	
13 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00	
14 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	80.00	1 JOB	80.00	
15 WHEEL ALIGNMENT	120.00	1 T	120.00	
16 COMPUTER RESET	450.00	1 JOB	450.00	
			2,650.00	2,650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: