

ASS. REC. BY:

REF:

EQ/20009555/1K6

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

14/1/19 11:00 AM Confirmed

Veh No:

SD1192113

Yr Regn: 12, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo S90

c.c.

1989

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

88704

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

YVIPS10B0141008759

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

23/8/20

D.O.I.

8/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S M

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block, MND Complex
Singapore 069110

Estimate No: ES2000083
Date: 08 Sep 2020

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 25/08/2020
TP Veh Reg No: SJD5848Z

Policy No:
Veh Reg No: SDH9211J
Make/Model: VOLVO S90 T5
MOMENTUM
Chassis No: YV1PS10BDH1006759
Engine No: B4204T231801480
Reg. Date: 28/12/2016

Estimate Repair Cost to Vehicle No :SDH9211J

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 FRONT WHEEL RIM - RH <i>1050</i>	1,250.00	1 PC <i>nd/61</i>	1,250.00	—
2 FRONT TYRE - RH	450.00	1 PC <i>sn</i>	450.00	X
			1,700.00	1,700.00
Spare Parts				
3 FRONT BUMPER	2,250.00	1 PC <i>R</i>	2,250.00	X
4 FRONT BUMPER PARKING SENSOR	368.50	1 PC <i>sn</i>	368.50	X
5 FRONT BUMPER SIDE RETAINER - LH	90.80	1 PC <i>sn</i>	90.80	X
6 FRONT BUMPER SIDE RETAINER - RH	90.80	1 PC <i>sn</i>	90.80	X
7 FRONT BUMPER CLIPS	60.00	1 SET <i>nn</i>	60.00	X
8 HEAD LAMP - RH	3,250.10	1 PC <i>sn</i>	3,250.10	X
9 FRONT FENDER - RH	885.50	1 PC <i>R</i>	885.50	—
10 FRONT FENDER SPLASH SHIELD - RH	285.90	1 PC <i>sn</i>	285.90	—
11 FRONT FENDER SPLASH SHIELD CLIP	80.00	1 SET <i>nn</i>	80.00	—
			7,361.60	7,361.60
Labour				
12 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,000.00	1 JOB	1,000.00	3001
13 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00	2201
14 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	80.00	1 JOB <i>nn</i>	80.00	X
15 WHEEL ALIGNMENT	120.00	1 T	120.00	601
16 COMPUTER RESET	450.00	1 JOB <i>nn</i>	450.00	X
			2,650.00	2,650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block, MND Complex
Singapore 069110

ATTN: Motor Claim Department

Your Ref No: —
Claim Type: Third Party
Accident Date: 25/08/2020
TP Veh Reg No: SJD5848Z

Estimate No: **ES2000083**
Date: 08 Sep 2020
Policy No:
Veh Reg No: **SDH9211J**
Make/Model: VOLVO S90 T5
MOMENTUM
Chassis No: YV1PS10BDH1006759
Engine No: B4204T231801480
Reg. Date: 28/12/2016

Estimate Repair Cost to Vehicle No :SDH9211J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 11,711.60
			Add GST @ 7%	819.81
			Total Amount Payable	<u>S\$ 12,531.41</u>

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FIVE HUNDRED THIRTY ONE AND CENTS FORTY ONE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE