

Not Notion
 11 Sep @ 8150h
 Recovery After Painting

ESTIMATE TO REPAIR

VEHICLE NO. : SDU 1750 D
 MAKE : MERCEDES BENZ
 MODEL : C 180 KOMPRESSOR
 YEAR : 2012
 CHASSIS NO : WDD2040452A741423

SURVEYOR NAME : LK
 DATE OF SURVEY : 10 SEP 2020
 TIME OF SURVEY :

DATE : 5-Sep-20
 DATE OF ACCIDENT : 4-Sep-20
 THIRD PARTY REF : SKP 5287 S
 THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper			\$ Bu 1,370.00	✓
1 pc	rear bumper reinforcement 615			\$ Bu 740.00	✓
2 pcs	rear bumper retainer		\$ 42.00	\$ Bu 84.00	x
1 pc	rear bumper chrome moulding - centre			\$ Bu 200.00	✓
2 pcs	rear bumper chrome moulding - side		\$ 144.00	\$ Bu 288.00	✓
1 pc	rear end panel			\$ Bu 1,380.00	x
1 pc	rear boot lid			\$ Bu 1,380.00	✓
1 pc	rear boot lock			\$ Nd 325.00	✓
1 pc	rear boot star			\$ Bu 50.00	✓
1 pc	rear boot C180 emblem			\$ Bu 90.00	✓
1 pc	rear boot kompressor emblem			\$ Bu 116.00	✓
1 pc	front bumper			\$ Bu 1,310.00	✓
1 pc	front bumper reinforcement			\$ Bu 380.00	✓
1 pc	front bumper number plate griller			\$ Bu 145.00	x
2 pcs	front bumper retainer		\$ 90.00	\$ Bu 180.00	x
1 pc	front grille			\$ CM 750.00	✓
1 pc	front grille inner bracket			\$ CM 28.00	✓
2 pcs	head lamps		\$ 1,100.00	\$ 2,200.00	✓
	Less 10%			\$ 11,016.00	
				\$ 1,101.60	
				\$ 9,914.40	
1 set	rear bumper sensor	S.Nett		\$ Nd 400.00	✓
1 set	number plate	S.Nett		\$ Nd 80.00	✓
	To putty & spray paint			\$ 1,200.00	800
	To check front wiring & focus head lights			\$ 30.00	200
	To check rear wiring & water leakage			\$ 30.00	200
	To anti-rust			\$ 80.00	300
	Labour Charges			\$ 800.00	700
TG/VL	TOTAL			\$ 12,534.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____