

ASS. REC. BY:

REF:

AG / 2000 9604/Ke

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 8/30 Person Contacted: _____

Vehicle: IN / OUT

Veh No: STY 5924B Yr Regn: 09, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M. E 300 c.c. 2996Colour: M. Brown A/C: Insured / Std / NI / NASp. Reading: 79604 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2120542A 265552

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 245/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front: _____

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 27/8/20D.O.I. 8/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ GIA & Est not ready4/1 11 Rm @ 3500 3850 Cmt

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Fines

Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY #07-16

SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

*Not Authorized
11 Sep @ 3850/-
Resurvey After Paint*

Estimate : QUOT202009-000194(00)

Date : 08/09/2020

Vehicle No. : SJY5924B

Make/Model : MERCEDES BENZ E 300

Mileage (km) : 0

Chassis No. : WDD2120542A265552

Accident Date : 27/08/2020 00:00:00

Claim No. : SLL4264Z

Reference : JO202009-0276

Policy No. : 5067521041-05

S/No	Particular	3days Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	RH taillamp	1.0	738.00	738.00 X
2	Rear bumper <i>1698</i>	1.0	1,820.00	1,820.00 ✓
3	Rear Bumper chrome LH	1.0	185.00	185.00 ✓
4	Rear bumper chrome - RH	1.0	185.00	185.00 ✓
5	Rear bumper chrome centre	1.0	215.00	215.00 ✓
6	Rear bumper sponge	1.0	162.00	162.00 X
7	Rear bumper reinforcement	1.0	910.00	910.00 ✓
8	Rear bumper side retainer	2.0 <i>dis/dit</i>	55.00	110.00 ✓
9	Rear bumper side bracket	2.0 <i>dis/dit</i>	98.00	196.00 ✓
10	Rear Bumper center bracket	1.0	115.00	115.00 X
11	Rear Bumper Lower lid <i>497</i>	1.0 <i>dis/crm</i>	595.00	595.00 ✓
12	Rear Bumper clips	12.0	9.00	108.00 ✓
13	Rear boot logo	1.0	58.00	58.00 ✓
14	Rear boot emblem - 7G TRONIC	1.0	66.00	66.00 ✓
15	Rear boot emblem - E300	1.0	98.00	98.00 ✓
16	Rear bumper lower bracket	2.0	36.00	72.00 ✓
17	RH exhaust chrome dip	1.0	215.00	215.00 ✓
List Total :				5,848.00
10% Discount S\$				584.80
				5,263.20

LABOUR :

* Towing charge	1.0 <i>(with bill)</i>	80.00	80.00 ✓
- To check wiring and lighting	1.0	45.00	45.00 ✓
- To remove and refit exhaust muffler	1.0	120.00	120.00 ✓
- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	500.00	500.00 ✓
- Spray painting on affected & replace parts	1.0	700.00	700.00 ✓
			1,445.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202009-000194(00)

Date : 08/09/2020

Vehicle No. : SJY5924B

Make/Model : MERCEDES BENZ E 300

Mileage (km) : 0

Chassis No. : WDD2120542A265552

Accident Date : 27/08/2020 00:00:00

Claim No. : SLL4264Z

Reference : JO202009-0276

Policy No. : 5067521041-05

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY #07-16

SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

E. & O.E.

Total S\$: 6,708.20

GST 7% S\$: 469.57

Amount Due S\$: 7,177.77

for CITY AUTO PTE LTD