

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHD6260K
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Sep 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2019
Engine No.:	2ZR2F31010
Chassis No.:	JTDKB3FU603089182
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	26 Dec 2019
First Registration Date:	26 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$23,328.00
Total Rebate Amount:	\$34,225.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Sep 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/09/2020 12:45
Date Of Accident 04/09/2020 10:10
Exact Location Of Accident JUNC OF JLN LIMAU KASTURI/JLN LIMAU MANIS
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD6260K
Insured/Policyholder
Name Of Registered Owner SMRT TAXIS PTE LTD
Co Reg No 1XXXXX369K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-80000000

Vehicle Particulars

Manufacturer TOYOTA
Model PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY
Fleet Policy YES
Policy Number D-20095484MFSH
Cover Note Number

Driver

Name of Driver SIM KENG LIM
NRIC No SXXXXX159Z
Date Of Birth 18/08/1952
Occupation OUTDOOR
Date Of Driving Pass 23/10/1970
Driving Experience 49 YEARS AND 10 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-80000000
Fax Number
Contact Number
Email Address NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG JALAN LIMAU KASTURI WITH ONE FEMALE CHINESE PASSENGER, SUDDENLY THE VEHICLE SMD7975R FROM THE RIGHT CAME OUT , AS A RESULT, THE VEHICLE SMD7975R HIT ONTO RIGHT FRONT OF MY TAXI

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMD7975R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LEWIS
 NRIC/Passport Number
 Contact Number
 Address
 Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



A - SHD 6260K
B - SMB 7975R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number : TAX/09/20/2009
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD8260K

Company Type : SMRT Taxicab Pte Ltd
 Estimation ID : EST-12533-ID
 Assigned By : Tan Lee Ge #

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 04/09/2020 02:10 AM
 Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Final Price(\$)	Repair/ Replace	Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)			Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	977.80	977.80	25.00	733.35	Replace	1	733.35	Replace	✓ / CR 4
One Time Key In	Main			LINER, FR FENDER, RH	1	202.50	202.50	25.00	151.88	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			RETAINER, FR WHEEL RH	1	3.20	3.20	25.00	2.40	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PROTECTOR, FR FENDER RH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PAD, FR WHEEL RH	1	59.60	59.60	25.00	44.70	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, RH	1	979.40	979.40	25.00	734.55	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			WHEEL, DISC FRONT	1	1,879.40	1,879.40	25.00	1,409.55	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	1	668.90	668.90	25.00	501.67	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	211.50	211.50	25.00	158.63	Replace	0	0	Not Give	✓ X SVC

Total Spare Part Cost 5,967.23

Surveyor Total 774.30

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 5,967.23

Final Sur Total 774.30

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	128.74	128.74	0.00	128.74	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,438.80	1,438.80	10.00	1,292.94	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	108.60	108.60	25.00	81.45	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			COVER, FR BUMPER	1	521.00	521.00	25.00	390.75	Replace	1	0	Repair	✓ X R
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	80.10	80.10	25.00	60.07	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			MOULDING, FRONT BUMPER SIDE, RH	1	95.60	95.60	25.00	71.70	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	✓ / Nec
Total Spare Part Cost									5,967.23	Surveyor Total 774.30				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									5,967.23	Final Sur Total 774.30				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	507.00	200	✓
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200	✓
Total:			1,116.00	400.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY RIM	180.00	0	
3	Main	TO REPSRAY FRONT BUMPER	378.00	200	/
4	Main	RESPRAY MIRROR COVER RH	180.00	0	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
2	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	/
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			600.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,967.23	774.30
Total Labour Cost	507.00	200.00
Total Spray Painting	1,116.00	400.00
Other	600.00	80.00
Overall Total	8,190.23	1,454.30
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	1,454.30
Surveyor Approved Amount		1,454.30
No of Repair Days*	5	3 <i>days</i>
Remarks	-	P/P, Before paint photo


Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Sun Pin (LKK)

Signature



Save

Clear

Survey Date

04/09/2020

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: