

ASS. REC. BY: Steve REF: _____

ASSIGNMENT

From: PRS Date: _____
Estimated Cost: _____
OD: (TP) WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJA6697B Yr Regn: 17/12/97
Type: (M.Cat) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Stream c.c. 1799
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 246896 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: RN61960999
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brakes: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45R17
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Kumho
Front R/Bal. 5 mm Rear R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 5/9/20 D.O.I. 9/9/20
Survey held at Garage 13
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear LH
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-ISK</u>

Date/Time, File Pass to? ☐ : Prell. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Formed: _____

Lump Sum / L.E.H. : _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

(1)Distorted (2)Cracked (3)Cut (4)Scratched
(5)Shifted (6)Buckled (7)Broken (8)Necessary (9)Missing
(10)Unconfirmed (11)Not Working

MOTOR CAR (LH)

ACTION (AC)
(1)Replace (✓) (2)Repair (X) (3)Check (✓)
(4)Not Consistent (NC)

Aug 2005

Vehicle No:

SJA 6697B

INC	Item	CON	AC	Qty
995326	Frt LH Door			
995140	Frt LH Door Protector			
995104	Frt LH Door Hinge			
995142	Frt LH Door Wing Mirror			
995102	Frt LH Door Garnish			
991593	Frt LH Door Glass Outer Moulding			
991588	Frt LH Door Glass Inner Moulding			
995103	Frt LH Door Glass			
991595	Frt LH Door Glass Regulator			
991596	Frt LH Door Glass Regulator Motor			
991662	Frt LH Door Rubber			
991636	Frt LH Door Outer Handle			
991607	Frt LH Door Inner Handle			
991625	Frt LH Door Lock w/Key			
991624	Frt LH Door Lock			
991562	Frt LH Door Central Lock			
991675	Frt LH Door Switch			
991617	Frt LH Door Inner Trim Board			
991568	Frt LH Door Checker			
991575	Frt LH Door Felt			
991688	Frt LH Door Wire Harness			
991683	Frt LH Door Window Glass Pillar			
991640	Frt LH Door Outer Pillar			
991613	Frt LH Door Inner Pillar			
991646	Frt LH Door Pillar Inner Garnish			
990554	Centre Pillar LH			
990542	Centre Inner Pillar LH			
990517	Centre Pillar Upper Garnish LH			
990564	Centre Pillar Lower Garnish LH			
991670	Frt LH Door Step Garnish			
994052	Rocker Panel LH			
994049	Rocker Panel Inner Panel LH			
994046	Rocker Panel Garnish LH			
994055	Rocker Panel Outer Side Skirt LH			
991300	Frt Bumper			
991325	Frt Bumper Bracket			
991462	Frt Bumper Side Retainer			
991433	Frt Bumper Reinforcement			
991468	Frt Bumper Sponge			
991427	Frt Bumper Protector			
991301	Frt Bumper Moulding			
991407	Frt Bumper Lower Spoiler			
995153	Frt LH Headlamp Assy			
995088	Frt LH Side Lamp			
995070	Frt LH Fender			
995147	Frt LH Fender Lamp			
995148	Frt LH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	DD	✓	
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge	BT	✓	2
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock	BT	✓	
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit	BR	✓	
992958		Rear Bumper	BR	✓	
992976		Rear Bumper Bracket	BR	✓	2
993068		Rear Bumper Side Retainer			
993045		Rear Bumper Reinforcement			
993077		Rear Bumper Sponge			
993040		Rear Bumper Protector			
993026		Rear Bumper Moulding			
993023		Rear Bumper Lower Spoiler			
993851		Rear LH Taillamp	DD	✓	
993436		Rear LH Fender	DD	✓	
993449		Rear LH Fender Protector	DD	✓	
990247		Sticker			
		LH Rear Sport Rim	CH	✓	
		LH Rear Tyre	TN	✓	
		LH Rear Wheel Bearing			

No of Items: _____

Assessor: _____

7 repair days