

ASS. REQ. BY:

Steve

REF:

CC4/LPC 2000 9625/p93

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / IP / INS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

MK-90K

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Formed:

Lump Sum / L.P.A. (C)

Veh No:

S66 239J

Yr Regn:

20/7/18

Type: M Ca / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make:

Volkswagen Touan

c.c

1395

Colour:

White

A/C:

Insured / Std / Nil / NA

Sp. Rending

405.72

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

WVG 222 IT 2JW 108563

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / Std / STD A/Rm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

25/8/20

D.O.I.

11/9/20

Survey held at

Volkswagen

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	165J
Vehicle Details	
Vehicle No.:	SGG239J
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4 TSI CL 5T13NZ HLG
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	CZD139122
Chassis No.:	WVGZZZ1TZJW108563
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$22,492.00
Original Registration Date:	20 Jul 2018
First Registration Date:	20 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$23,489.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jul 2028
PARF Rebate Amount:	\$17,616.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,501.00
COE Rebate Amount:	\$30,241.00
Total Rebate Amount:	\$47,857.00

The information contained herein is correct as at 11 Sep 2020

OK