



Case Details

Case Reference Number : TAX/09/20/2005
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF125Y

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-12523-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 02/09/2020 11:25 PM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	364.20	Replace	✓	CR4
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	332.70	332.70	25.00	249.52	Replace	0	0	Check	✓	X Svc
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	120.10	120.10	25.00	90.07	Replace	0	0	Check	✓	X Svc
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	120.10	120.10	25.00	90.07	Replace	0	0	Check	✓	X Svc
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	1	11.00	11.00	25.00	8.25	Replace	1	8.25	Replace	✓	NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	1	4.00	4.00	25.00	3.00	Replace	1	3.00	Replace	✓	NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	1	4.00	4.00	25.00	3.00	Replace	1	3.00	Replace	✓	NEC
One Time Key In	Main			PAD, RR BUMPER, CTR	3	11.00	33.00	25.00	24.75	Replace	3	24.75	Replace	✓	NEC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	1	11.30	11.30	25.00	8.48	Replace	1	8.48	Replace	✓	NEC
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	1	4.50	4.50	25.00	3.38	Replace	0	0	Not Give	✓	X Svc
Total Spare Part Cost									4,909.10	Surveyor Total					842.26
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)					0
Final Spare Part Cost									0.00	Final Sur Total					842.26

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	1	99.45	Replace ✓ /BR
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			SEAL, RR BUMPER, RH	1	118.30	118.30	25.00	88.72	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			SEAL, RR BUMPER, LH	1	118.30	118.30	25.00	88.72	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace ✓ /NEC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	374.50	374.50	25.00	280.88	Replace	1	280.88	Replace ✓ /CR4.
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	22.00	22.00	25.00	16.50	Replace	1	16.50	Replace ✓ /Mis.
One Time Key In	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	39.00	39.00	25.00	29.25	Replace	0	0	Bracket Cracked ✓ X Svc ✓
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	175.10	175.10	25.00	131.32	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	241.90	241.90	25.00	181.43	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	229.90	229.90	25.00	172.43	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	339.60	339.60	10.00	305.64	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			LAMP ASSY, REAR, RH	1	293.60	293.60	10.00	264.24	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	651.00	651.00	25.00	488.25	Replace	0	0	Check ✓ X Svc
Total Spare Part Cost									4,909.10	Surveyor Total 842.26			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0			
Final Spare Part Cost									0.00	Final Sur Total 842.26			

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give ✓ X sue
One Time Key In	Main			WHEEL, DISC	1	1,879.40	1,879.40	25.00	1,409.55	Replace	0	0	Not Give ✓ X sue
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give ✓ X sue
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	211.50	211.50	25.00	158.63	Replace	0	0	Not Give ✓ X sue
Total Spare Part Cost									4,909.10	Surveyor Total 842.26			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0			
Final Spare Part Cost									0.00	Final Sur Total 842.26			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY REAR PANEL	180.00	0	
4	Main	TO RESPRAY RIM	180.00	0	
Total:			918.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
2	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
Total:			600.00	50.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			600.00	50.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	0.00	842.26
Total Labour Cost	507.00	200.00
Total Spray Painting	918.00	200.00
Other	600.00	50.00
Overall Total	2,025.00	1,292.26
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	1,292.26
Surveyor Approved Amount		1,292.26
No of Repair Days*	5	2 <i>2 days</i>
Remarks	-	P/P, before paint photo.
Surveyor Name		Sun Pin (LKK)
Signature		

Save Clear

Survey Date

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Supplementary Parts

- Pixel Sticker 2 \$60.00 each

\$120.00 ✓ Nec