ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 1800062546

Claims No. 1342674426SG

Sum Insured: Excess: 800

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKF2517B. Yr Regn: 2018 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A6. c.c 1798.

Colour Bronze. A/C: Insured / Std / NI / NA

Sp.Reading 30341 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ4G6JN034633

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17.

R: 225/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	09/09/20.

Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD A1G.
	MV : 130K confirm repair cost of $21,175.84 @ 7 days
	PV : 69.6K. red:18627.16;46%
	Nett : 60.4K

Date/Time. File Pass to? 1)

Date/Time. File Return to? 2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 7

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($ ☐ : Interview ($ ☐ : Tech. Insp ($ ☐ : Weather ($

Survey Fee:

Transportation: S + PS S

Photos

Other:

Total

Report Format :

Lump Sum / MC Value: 21175.84