

CS/ICS20009642/Esf3

ASS. REC. BY:

Stew

REF:

CS/ICS 20009642/f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBK 3095A

Yr Regn:

30/3/20

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV350

c.c. 2488

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

7212

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNIMC2E2620031651

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inter / Jammed / Leaked / Burnt or

Brake: Inter / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / A/Rim or

Tyre Size:

F:

185R15C

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 8

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

7/9/20

D.O.I.

19/9/20

Survey held at

Efficient motor

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Frm RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-60K

STEVE CONFIRMED L/S \$ 4,250.00/4 DAYS WITH EZEL
(\$ 3,851.85/RED - 48%)

Date/Time, File Pass to?

16/09/2020

1) TYPIST

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Formed:

Lump Sum

L/S \$ 4,250.00