



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD c/o SEDGWICK SINGAPORE PTE LTD 30 CECIL STREET, LEVEL 12 PRUDENTIAL TOWER SINGAPORE 049712			Ref: CS/SGK20009649/R1tf3e2 Date: 14/04/2021 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	UNREGISTERED BUS	
Policy No.	MSIG: 628043 PLY	Coverage (\$)	0.00	
Claim No.	SGK: 6001341/AR	Excess (\$)	0.00	
Assign From	ABRAHAM RAJADURAI	Assign Date	09/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	YS2K6X20001915732	Colour	MULTI COLOUR	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	MICHELIN	8 mm	
L/H Front Tyre	295/80 R22.5	MICHELIN	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	MICHELIN	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	MICHELIN	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2020	Inspection Date	09/09/2020	
Survey held at	SNL CONSTRUCTION AND TRANSPORT SERVICES PTE LTD 31 GUL CIRCLE, SINGAPORE 629569			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		