



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD
c/o SEDGWICK SINGAPORE PTE LTD
30 CECIL STREET, LEVEL 12
PRUDENTIAL TOWER SINGAPORE 049712

Ref: CS/SGK20009649/R1f3e2

Date: 14/04/2021

Code: MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	UNREGISTER BUS
Policy No.	MSIG: 628043 PLY	Coverage (\$)	0.00
Claim No.	SGK: 6001341/AR	Excess (\$)	0.00
Assign From	ABRAHAM RAJADURAI	Assign Date	09/09/2020

2. Vehicle Particulars & Condition

Make & Model	SCANIA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	YS2K6X20001915732	Colour	MULTI COLOUR
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	MICHELIN	8 mm
L/H Front Tyre	295/80 R22.5	MICHELIN	8 mm
R/H Rear Tyre	295/80 R22.5 (D)	MICHELIN	8/8 mm
L/H Rear Tyre	295/80 R22.5 (D)	MICHELIN	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/08/2020	Inspection Date	09/09/2020
Survey held at	SNL CONSTRUCTION AND TRANSPORT SERVICES PTE LTD 31 GUL CIRCLE, SINGAPORE 629569		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**