

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305421641
Date : 09-09-20
Time of Fax: _____

Via Fax : EMAIL
Your Insured: SKT 6949M
Date of Acc : 08-09-20

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH 7144Z

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident _

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

♦ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} jumanibm@cde.com.sg Fax no. 6546 8156
♦ <u>Jumani Bin Masudin</u>	<u>Tel: 6214 8315 or HP: 9635 5305</u>	
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
♦ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	
♦ Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176	

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President
Crash Repairs & Claims Recovery

Date/Time: 09.09.2020 14:20

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.: 305421641

OWNER

AS COMFORT TRANSPORTATION PTE LTD
OWNER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (O)
(P)

QUANTITY CARD NO.

REGN NO.

SH 7744Z

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN 09.09.2020 12:30

YR OF MANU.

09.06.2016

TARGET DATE

CHASSIS CODE


KMHLB41UMGU090118

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 08.09.2020
NATURE: 3P 08.09.2020/C

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Delivery Slip

Exit Pass

No.: SH 7744Z JU AIG

Vehicle No.: SH 7744Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 09.09.2020

REPAIR ESTIMATE

Time: 14:29:32

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305421641
REGN NO : SH 7744Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 09.06.2016
DATE/TIME IN : 09.09.2020 12:30
ACCIDENT DATE : 08.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER W LIP & FOG LAMP C	1	1,052.20	20.00	841.76
0002 04-01-0103-0781-A	I40VC LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40
0003 04-01-0103-0574-A	I40VC PANEL-FENDER LH+	1	663.00	20.00	530.40
0004 04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68

SUB-TOTAL : 2,502.24

JOB NATURE

0000 PB	PANEL BEATING	600.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 17-01	CHECK ALL LIGHTING	50.00
0003 20-05	RENEW ADVERTISMENT STICKER-	100.00

SUB-TOTAL : 1,250.00