

LKK- HIG (LISU)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 09.09.2020

Time: 14:29:32

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305421641
REGN NO : SH 7744Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 09.06.2016
DATE/TIME IN : 09.09.2020 12:30
ACCIDENT DATE : 08.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER W LIP & FOG LAMP C	1	1,052.20	20.00	841.76	de ✓
0002 04-01-0103-0781-A	I40VC LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40	X
0003 04-01-0103-0574-A	I40VC PANEL-FENDER LH+	1	663.00	20.00	530.40	RY
0004 04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	de ✓

SUB-TOTAL : 2,502.24

JOB NATURE

0000 PB	PANEL BEATING	600.00	420
0001 SP	SPRAYPAINT CHARGE	500.00	400
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-05	RENEW ADVERTISEMENT STICKER-	100.00	(net)

SUB-TOTAL : 1,250.00

Tan Hin 9749 5749
2 days 9/9/2020 pm
L/S Resurvey after repair
for Mr C Khamborn.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORT DELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

200, Orchard Road, Singapore 238873

Telephone : 6342 8888 Fax : 6342 8889 E-mail : info@cdg.com.sg

Website : www.cdg.com.sg

CDG is a member of the ComfortDelGro Group

CDG is a member of the ComfortDelGro Group

CDG is a member of the ComfortDelGro Group

CDG is a member of the ComfortDelGro Group

CDG is a member of the ComfortDelGro Group

CDG is a member of the ComfortDelGro Group

CDG is a member of the ComfortDelGro Group

CDG is a member of the ComfortDelGro Group

Member of COMFORT DELGRO

Date/Time: 09.09.2020 14:20

Page: 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

Job No: 305421641

Customer

AS COMFORT TRANSPORTATION PTE LTD
 7010045
 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 65508755

(R) (O)

(P)

OUNT CARD NO.

REGISTRATION SH 7744Z

MAKE HYUNDAI

MODEL I-40

YEAR MANUF 09.06.2016

CHASSIS NO KH01L841UMF0090118

BAR CODE

FUEL

E 1/2

DATE/TIME 09.09.2020 12:30

DATE/TIME

DATE/TIME


JOB DESCRIPTION

Accident Date: 08.09.2020
 NATURE: 3P 08.09.2020/C

3/NO

LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

Payment Slip

CUSTOMER'S SIGNATURE

Exit Pass

Vehicle No

SH 7744Z

SH 7744Z

JU AIG

Signature/Date

Name of Service Advisor