





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/09/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5585J
Case Reference Number	BUS/08/20/7018
Registration Date	24/11/2016
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	VOLVO
Name of Driver	Shen Zhengqiang
Type of Accident	Side Swipe
Accident Date and Time	29/8/2020 5:45 PM
Accident Reported Date and Time	29/8/2020 6:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108081
Special Instruction to ARC,if any	SG5585J-RIGHT FRONT PORTION SKM5800Y (TP) INSURED WITH
Prepared Date and Time	4/9/2020 10:45 AM
Chassis Number	YV3S4P922GA179948
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$530.00
Total Spray Cost	\$616.00	\$432.00
Total Spare Part Cost	\$701.84	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,377.84	\$962.00
Lump Sum Total	\$2,400.00	\$0.00
Number of Repair Days	3.0	1.0
Prepared / Adjusted By	Kok Khoon Goh	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	04/09/2020 10:53 AM	07/09/2020 3:14 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/09/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$1,060.00				\$530.00			
Total Labour		\$1,060.00				\$530.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$616.00				\$432.00			
Total Spray Painting & Panel Beating		\$616.00				\$432.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012094	Body	ATP-03155	N/S CORNER BUMPER	1.00	\$974.78	100.00	\$0.00	Replace	Repair XR
6012097	Body	ATP-02807	N/S CORNER DEFLECTOR	1.00	\$328.33	100.00	\$0.00	Repair	Repair XR
Total					\$1,303.11		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1 days

536  
432  
-----  
962

PIP  
\$962