

Our Ref : T 0920 / SH 8961G /KS(st)
Your Ref: _____
Date : 18-Sep-2020

CDGE Taxi Claims Dept
59 Loyang Drive 4th Floor
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimilie +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building

78 Shenton Way

#07-16

Singapore 079120

Attn : Motor Claims Department

Dear Sir

WITHOUT PREJUDICE

**ACCIDENT INVOLVING OUR TAXI SH 8961G YOUR INSURED SML6434A
AND OTHER SJW5064T ON 9-Sep-2020**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No SH 8961G which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SML6434A we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,230.50
2	<u>2</u> days Loss of Rental @ \$ 116.95 per day	\$ 233.90
3	Survey Report Fees (<i>Surveyed by M/s LKK</i>)	\$ -
4	GIA / LTA Search Fees	\$ 2.00
5	GIA / Police Report Fees	\$ -
6	Towing Fee	\$ -
		\$ 1,466.40

HIRER'S CLAIM

7	<u>2</u> days Loss of Income @ \$ 80.00 per days	\$ 160.00
	Total Claims :	\$ 1,626.40

We enclose herewith the following documents to support the claims: -

- Original repair bill :
- LTA search slip/s of : SML6434A
- GIA / Police report/s of : SH 8961G
- Letter of authority from owner / hirer / operator
() Photograph/s of Accident Scene () Certificate of Insurance
() Witness statement/s () PIR (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Kazali Hj Selahudin

CDGE Taxi Claims Department

Tel : 6214 8736 Fax : 6214 1843 Email : kazali@cdge.com.sg

This is a computer generated letter. No signature is required.

Our Ref: CT20090123

Date: 15 September 2020



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 09/09/2020 @ 21:00 hrs
ALONG TAMPINES AVE 2 X AVE 5
INVOLVING SML6434A, SJW5064T

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH8961G** (the "Taxi"). The Taxi was hired to **TAN KAY TONG IC NO SXXXX412I** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$116.95** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Manager, Fleet Safety

This is a computer generated letter. No signature is required.

DATE	NAME OF DRIVER	MILEAGE READING		MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		NAME OF DRIVER
		FROM	TO		FROM	TO	
6/9	TAN KAY	3930	28	542	1908	8.18	
7/9	Choo	3932	01	153	0840	1900	
7/9	TAN KAY	3934	36	234	19.50	7.18	
8/9	Choo	3935	92	166	0735	1905	
8/9	TAN KAY	3938	64	265	19.18	7.50	
9/9	Choo	3939	97	150	0740	1900	
9/9	TAN KAY	3942	00	201	19.38	7.38	
10/09/20	Accident			Loyang	0950	—	
11/09/20	Repair	TAN KAY	Tan		—	1200	

DATE	NAME OF DRIVER
11/10	
12/10	
13/10	
14/10	
15/10	
16/10	
17/10	
18/10	
19/10	
20/10	
21/10	

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING i 40 SH8961G , SML6434A , SJW5064T ON 09-Sep-20 21:00
ALONG TAMPINES AVE 2 X AVE 5**I / We **TAN KAY TONG** (Hirer) NRIC No.: **SXXXX412I**and/or (Relief) NRIC No.: **SXXXX412I**Taxi Number **SH8961G**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **10-Sep-2020**Name of Hirer **TAN KAY TONG**Hirer NRIC **SXXXX412I**

Signature :

Address **896 TAMPINES STREET 81 #02-886
520859**Contact No. **83728791**

TP Insurer Enquiry

ENQUIRY DETAILS

Accident Date	09/09/2020
NRIC/FIN or Co. Reg. No.	
Vehicle No.	SML6434A

Policy Details

Req. By	Req. Date	Search	Enq. Accident Date	TP Insurer	Tel No.	Period of Insurance	Status	Action
Catherine Por Moy Juan [ComfortDelGro Engineering Pte Ltd]	10/09/2020 10:45	SML6434A	09/09/2020	AIG Asia Pacific Insurance Pte. Ltd.	65-6419- 3000	29/05/2020- 28/05/2021		Receipt

Note:

- All submitted enquiry will be recorded and you can refer back from the History.

SM 8961C

TAX INVOICE

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Marine + 65 6383 6280 Facsimile + 65 6280 9735
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY, AIG BUILDING #07-16
SINGAPORE 079120

CONTACT NO: 64193000 3225094

Description : 3P 09.09.2020

VEHICLE NO SH 8961G
MAKE HYUNDAI
MODEL I-40
DATE OF REG 13.12.2017
CHASSIS CODE KMHLB41MHU098595
JOB NO. 305421649
NO/DATE 91524095 15.09.2020
JOB TYPE ODOMETER READING

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt 1,150.00
Add GST @ 7.000 % 80.50
Total Invoice amount 1,230.50

Issued by : KATHERINETAN 15.09.2020 16:28:17
Repair Type : CLSO/57/57
Payment Type/Term : /credit 30 days

WHILE TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CAR OR OTHER PROPERTY BELONGING TO CUSTOMERS AND DRIVERS AT CUSTOMERS SHALL INSPECT THEIR VEHICLE IMMEDIATELY AFTER REPAIR WORK IS COMPLETED. NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS CONCERNING THE WORK SHALL BE GIVEN BY CUSTOMERS WITHIN 7 DAYS FROM SUCH DELIVERY. INTEREST OF 1% PER MONTH WILL BE CHARGED ON A QUOTE BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DATE OF THE INVOICE OR WITHIN 30 DAYS FROM THE INVOICE FOR THE PURPOSE OF DEFAULT. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND NOTIFY THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT RECEIVE THE CUSTOMER'S COMPLAINT WITHIN THE ABOVE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
005 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.