

ALG-CLUM

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.09.2020

Time: 11:18:00

Page: 1

JY

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305421649
REGN NO : SH 8961G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.12.2017
DATE/TIME IN : 10.09.2020 09:50
ACCIDENT DATE : 09.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	dl
0002	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	Ry
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	dl
0004	04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	dl

SUB-TOTAL : 1,134.80

JOB NATURE

0000	PB	PANEL BEATING		300.00			200
0001	SP	SPRAYPAINT CHARGE		300.00			200
0002	L	REMOVE/REFIX REVERSE SENSOR				80.00	30

SUB-TOTAL : 680.00

TOTAL : 1,814.80

MVA NAME & SIGNATURE

DATE :

Tanjah 97495749
WP 10/4/20 @ 3pm
2 days
Worth it
pls bring after repair
fairly @ 11k.com

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: