

ALG- (Lisum)

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 10.09.2020  
Time: 11:18:00  
Page: 1

JM

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305421649  
REGN NO : SH 8961G  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 13.12.2017  
DATE/TIME IN : 10.09.2020 09:50  
ACCIDENT DATE : 09.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	dl	
0002	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	RY	
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	dl	
0004	04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	dl	952.40.

SUB-TOTAL : 1,134.80

JOB NATURE

0000	PB	PANEL BEATING		300.00		280	
0001	SP	SPRAYPAINT CHARGE		300.00		200	510.
0002	L	REMOVE/REFIX REVERSE SENSOR		80.00		30	

SUB-TOTAL : 680.00 1462.40.

TOTAL : 1,814.80 4/s \$1150 02 days #

MVA NAME & SIGNATURE  
DATE :

Tanjah 97495749  
'wp' 10/9/20 @ 2pm  
2 days  
Wentleu  
cls boxing after repair  
tanj@delgro.com

SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: