



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 17/18/18/VS29/263397

Date: 21st September 2020

Our Ref: CS1/LPM20009719/Gvd3s2

M/s Lonpac Insurance Bhd

21st Floor, Bangunan Public Bank

No. 6 Jalan Sultan Sulaiman

50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO. SKN 3669Y
INSURED VEHICLE NO. JNG 1037 ACCIDENT DATE 29.03.2018**

We thank you for your instruction on 11.09.2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKN 3669Y from M/s CA Appraiser.
- b) Polis Diraja Malaysia of Vehicles SKN 3669Y and JNG 1037.
- c) Colour damaged vehicle photographs of SKN 3669Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKN 3669Y
Make & Model	: Toyota Wish 1.8 A
Year of Registration	: 2006
Chassis Number	: ZNE100300952
Engine Capacity	: 1794 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.