

ASS. REC. BY: Taufik

REF:

TMI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC7345Z Yr Regn: 2017 / Per

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 46960 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 10M HLB410M H41000 69Gen. Cond: Good Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SR / STD A/Rim orTyre Size: F: 205/60R16R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Duracell

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 10/9/20Survey held at Comptelco Coyah

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TAUFIKH CONFIRMED P/P \$ 1,831.40/2 DAYS WITH HONG
(\$ 1,860.24/RED - 50%)

Date/Time, File Pass to?

18/09/2020

1) TYPIST

Date/Time, File Return to?

2)

Per. Format:

Lump Sum / P/P: P/P \$ 1,831.40

: Prel. Report



: Final Report

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



Survey Fee:

Transportation:

S + RS \$

Phone

Others

9/10/2020

Repairer Estimates

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Heng

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)

COPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	10/09/2020
Vehicle Reg. No.:	SHC7345Z	Driveable?	YES
Party At Fault:	UNKNOWN		

Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	15/12/2017
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4FDHU730647	Chassis No:	KMHLB41UMHU100069
Odometer:	0 KM		

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	4

Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)
-------------------	--

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	2,480.64
Labour	11.00
Paintwork Labour	1,200.00
Towing	0.00
	0.00

Gross Total (S\$)	3,691.64
+ GST 7.00% (S\$)	258.41
Nett Amount (S\$)	3,950.05

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference
 Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2020)
 Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHC7345Z/10/09/2020 15:47
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/Prices not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	20.00	0.00	Rx *1,025.20 FL
2	1		*FRONT FENDER RH	20.00	0.00	Ry *663.00 FL
3	1		*HEADLAMP ASSY RH	20.00	0.00	ant *1,388.00 FL
4	1		*FRONT BUMPER BRACKET RH	20.00	0.00	nn *24.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1388	3,100.80
- List Item Discount on L Items (S\$)		620.16
Total Parts (S\$)	1110.40	2,480.64

ComfortDelGro Engineering Pte Ltd/SHC7345Z/10/09/2020 15:47. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Repairer Estimates

Estimates on Miscellaneous Items

Particulars

Amount

Miscellaneous Items
ODTP Case (insurance)

✓ 11.00

Sub Total (S\$) 11.00 ✓

Estimates on Labour

Particulars

Lab.Type

Amount

Labour Items

PANEL BEATING
SPRAY PAINTING
CHECK WIRING
TUFF KOTE

New

~~320~~ 280 600.00

New

400 500.00

New

30 50.00

New

111 x 50.00

Gross Labour Cost (S\$) 710 1,200.00

ComfortDelGro Engineering Pte Ltd/SHC7345Z/10/09/2020 15:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97445749
WP

Dunstan

10/9/20 @ Spr

P/P, Resurvey new parts, after repair.

02 days

tanpin 11 days on.

1110.40

11

710

\$1831.40

#

2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: