

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. SKN8259P yr Regn: 2014 July
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Chervrolet Capiva c.c. 2384
 Colour Blue A/C: Insured / Std / NI / NA
 Sp. Reading 105770 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KL1CA264JE3040788
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/65R17
 R: 225/65R17

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>10/08/20</u>
Survey held at <u>First Network</u>	
Des. of Damages: <u>Fr</u> / <u>Rear</u> / O/S / N/S / U/C / Rooftop or	

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TT AIG

MV: 46K

Depreciation @ 9.5K x 3.8yr + Min. Perf = $(9.5 \times 3.8) + 10K = 46K$

PV: 38.9K

Nett: 7.1K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inv. (\$

☐ : Material (\$

Survey Fee:

Transportation:

3 x FS, \$

Photos

Other

Rep. of Form 42

Rep. of Form 42

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 399I

Vehicle Details

Vehicle No.: SKN8259P
Vehicle to be Exported: No
Intended Deregistration Date: 08 Sep 2020
Vehicle Make: CHEVROLET
Vehicle Model: CAPTIVA C140 2.4D FWD 6AT
Primary Colour: Black
Manufacturing Year: 2014
Engine No.: LE9141270064
Chassis No.: KL1CA26UJEB040788
Maximum Power Output: 123.0 kW (164 bhp)
Open Market Value: \$19,780.00
Original Registration Date: 22 Jul 2014
First Registration Date: 22 Jul 2014
Transfer Count: 0
Actual ARF Paid: \$19,780.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 21 Jul 2024
PARF Rebate Amount: \$12,857.00

Intended COE Rebate Details

COE Expiry Date: 21 Jul 2024
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$67,304.00
COE Rebate Amount: \$26,035.00
Total Rebate Amount: \$38,892.00

The information contained herein is correct as at 07 Sep 2020

OK

