



Merimen e-Claims



Used 2018 Ferrari Portofino 3.9A



Enquire Vehicle

mart.com/used_cars/info.php?ID=914480&DL=1000

► Ferrari Portofino 3.9A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$788,000

Depreciation ⓘ
\$70,430 /yr
View models with similar depreReg Date 22-Nov-2018
(8yrs 2mths 5days COE left)

Mileage 5,000 km (2.7k /yr)

Manufactured ⓘ 2018

Road Tax ⓘ \$3,724 /yr

Transmission Auto

Dereg Value ⓘ \$343,295 as of today (change)

OMV ⓘ \$250,443

COE ⓘ \$32,001

ARF ⓘ \$422,798

Engine Cap 3,855 cc

Power 441.0 kW (591 bhp)

Curb Weight ⓘ 1,675 kg

No. of Owners ⓘ 1

Type of Vehicle Sports Car

Features

3.9 L Twin Turbo V8 Engine Produces 590BHP, More Significant Torques Of 560 From 3000-5200 RPM. View specs of the Ferrari Portofino (2018)

Accessories

Forged Rims, Parking Sensors, yellow Brake Calipers, parking Camera, Yellow Stitching, Nero Daytona Colour, Black Interior.

Dc

ASS. REC. BY: Paul

REF:

CC4/A1420009762/Rika3

7202

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMP 99Cat Workshop m/s ITAL AUTOof 30, LENTH KET ROInsured: ML

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 876K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMP 99C Yr Regn: 2020 / FEBType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: FERRARI PORTOFINO c.c. 3855Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 3730 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZFF89FPC000250653Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____Modi: Nil / 3/Rim / STD A/Rim or _____Tyre Size: F: 245/352R20

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 06/09/2020D.O.I. 5/09/2020Survey held at ITAL AUTODes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / I.B.A. (\$) _____